

Aug 24, 2026

Meeting Aug 24, 2026 at 13:10 EDT

Summary

The team reviewed software development updates and finalized labor estimates for vehicle service and booking workflows.

System Booking Workflow Testing

Testing revealed critical interface bugs involving booking holds and vehicle data enrichment failures. Development identified necessary screen layout adjustments to address cramped navigation and saving logic issues.

Brake Service Labor Standardization

The team decided to standardize labor time for combined brake pad and rotor replacements to 60 minutes. This change ensures consistent pricing and workflow predictability across all shops.

Inspection Protocol Process Discussion

Participants explored splitting inspections into pre-checks and lift-based evaluations to improve technician accuracy. Logic updates allow timers to pause appropriately during these necessary inspection phases.

Decisions

Aligned

- **Brake and rotor service combination** Brake pad and rotor replacement is combined into a single service entry to avoid confusion and streamline the booking process.
- **Standard labor times for brake services** Brake pad replacement is set to 60 minutes and brake pad and rotor replacement is set to 90 minutes per axle.
- **Battery relearn process as separate item** Battery relearn procedures are established as a separate labor line item.
- **OEM parts requirement for transmission fluid** Transmission fluid parts are restricted to OEM options to ensure compliance with specific manufacturer certifications.
- **Tire brand categorization established** The tire brand selection is limited to specific tiers (high, mid, low) to ensure appropriate quality and prevent shops from selecting low-quality brands.
- **Specs match button interface updated** The 'specs match' button is redesigned as a floating element that remains visible during navigation, similar to DocuSign functionality, to improve user experience.
- **Stationary UI for saving status** The team agreed to implement a check mark icon placed on the left side of the UI for the saved status to eliminate layout shifting and bouncing.
- **Brake fluid five-tier grading system** The brake fluid level indicator will utilize a five-tier grading system consisting of Max, High, Mid, Low, and Min.
- **Brake fluid level diagram icon** An 'eye' icon will be added to the brake fluid level UI to provide a diagram explaining the various measurement levels to technicians.
- **Mandatory horn diagnostic process** Horn inspections are maintained as a required safety item, and failure will trigger a diagnostic process step before a replacement service is approved.

- **Multi-point inspection timing adjustment** The multi-point inspection workflow will be adjusted to trigger a popup requiring completion when the technician clicks 'start job' at the mechanical work phase.
- **Rotor stamp text collection removal** The requirement for technicians to collect and verify 'rotor stamp text' photos is removed from the inspection workflow.
- **Brake pad and rotor job consolidation** Brake pad and rotor replacement services will be consolidated into a single job line item for quoting to ensure accurate labor time calculations.
- **App price hike notification strategy** Users will be informed of expected price hikes for Jaws components specifically within the application interface.

We've **updated the Decisions section** using your feedback.

Let us know what you think: [Helpful](#) or [Not Helpful](#)

Next steps

- ☐ [The group] Adjust brake timing: Set the duration for brake pad replacement services to 60 minutes in the application.
- ☐ [The group] Set rotor timing: Update the brake pad and rotor replacement service to 90 minutes.
- ☐ [The group] Combine brake services: Combine individual brake pad and rotor services into a single selectable option in the application.
- ☐ [Yassin Wahman] Clean catalog: Remove the designated outdated times and services from the catalog.
- ☐ [developer setup] Fix VIN enrichment: Resolve the issue where the VIN enrichment popup fails to trigger during the walk-in booking process.
- ☐ [Yassin Wahman] Send Tire Lists: Send the tire category list to the development team to facilitate brand filtering.

- ☐ [developer setup] Limit Tire Brands: Implement a system to restrict tire brand selections based on user-selected quality tiers.
- ☐ [developer setup] Adjust UI Layout: Modify the schedule interface to ensure better visibility and alignment across different laptop screen resolutions.
- ☐ [developer setup] Enable Non-Original Equipment Manufacturer Parts: Update the system to permit the selection of aftermarket parts in addition to original equipment manufacturer options.
- ☐ [Daniel C] Update Booking Flow: Modify the booking interface to allow users to either accept the current held time or choose a new available time.
- ☐ [developer setup] Investigate M3 Service: Determine why the differential service for the M3 cannot be booked.
- ☐ [Abdelrahman Hamdy Akl (Abdul)] Submit Service Quote: Resubmit the service quote with a 3-day lead time to account for part sourcing.
- ☐ [The group] Test Rotor Booking: Verify that the rotor booking functionality is correctly integrated and operational.
- ☐ [The group] Fix Booking Bug: Correct the system error that causes the app to switch the selected car model during quote acceptance.
- ☐ [The group] Require Vehicle Specs: Mandate the collection of VIN or detailed vehicle specifications to ensure accurate part identification for quotes.
- ☐ [Daniel C] Fix Booking Logic: Ensure system automatically moves bookings to an available mechanic when a customer selects any mechanic, eliminating the need for manual rescheduling and client verification.
- ☐ [The group] Float Spec Match: Implement a floating spec matching box that remains pinned on screen to avoid continuous scrolling.
- ☐ [The group] Add Smooth Scrolling: Incorporate a navigation system with highlighted points that auto-scroll users to necessary sections.
- ☐ [The group] Standardize UI Elements: Update the save indicator to a left-aligned check mark to ensure UI consistency and prevent layout shifts.
- ☐ [Daniel C] Add Visual Help: Include an icon for visual diagrams that explain reservoir level definitions to technicians.
- ☐ [Daniel C] Fix Inspection Workflow: Modify the multi-point inspection system so that adding items to a job does not automatically conclude or submit the inspection. Ensure the user remains on the inspection screen instead of triggering a premature exit.

- ☐ [Daniel C] Fix Navigation: Update the navigation logic to prevent the application from moving away after a user marks a zone as complete. Maintain the current user position to support workflow continuity.
- ☐ [Yassin Wahman] Investigate Follow-up Logic: Analyze the software logic to determine if suggested follow-up services depend on service catalog availability or enrichment data. Clarify the specific conditions under which these recommendations appear.
- ☐ [Yassin Wahman] Test Transmission Recommendation: Record and re-test the transmission service recommendation feature to verify if it triggers under expected conditions. Confirm if non-catalog items are handled consistently.
- ☐ [The group] Update Inspection Popup: Configure the application to trigger a popup for detailed inspections like brake measurements only after the job timer starts. Ensure this preserves the integrity of the existing multi-point inspection process.
- ☐ [developer setup] Fix Coding System: Update the coding system to ensure it aligns with the rest of the website.
- ☐ [Daniel C] Lead Quote System: Manage the quote system development to improve consistency and accuracy.
- ☐ [Yassin Wahman] Send Meeting Notes: Forward the meeting notes and tire data to the development team.
- ☐ [Yassin Wahman] Finalize User Messaging: Finalize the documentation for language used when parts are missing to present to the user.
- ☐ [Yassin Wahman, Daniel C] Reconcile Brake Workflows: Schedule a meeting before Thursday to reconcile brake pad and rotor replacement job flows.
- ☐ [developer setup] Process Notes: Implement the tasks and fixes identified in the meeting notes provided by Yassin.


Details

Did the screenshots in this section make your notes [better](#) or [worse](#)?

- **Recent Software Development PR Updates:** Daniel Chelala provided a summary of recent software developments, noting that the quote system

remains an item to leave alone for the moment. Daniel Chelala reviewed several completed tasks, including the addition of a tire type field with options like run-flat, all-season, and touring; formatting the inspection sticker date to show the month rather than month and year; and improving the work timer to correctly pause and resume. Additional updates include status color coding, fixing post-job report suppression to prevent flagged items from showing as recommendations after work is completed, removing fluid top-off suggestions—excluding oil changes—and removing the toggle option for driver visibility on recommendations.

- **Walk-in Booking and Initial Brake Job Test:** Yassin Wahman initiated a walk-in booking test using the "Bookings" feature. Abdelrahman Hamdy Akl (Abdul) began the process by entering customer information and the 17-digit VIN to test the system's data population capabilities. Yassin Wahman proposed a brake pad replacement job to test the workflow, noting that a 90-minute estimate for front brake pads seemed high.



- **Brake Service Pricing and Standardization:** Abdelrahman Hamdy Akl (Abdul) and the team discussed the labor time estimates for brake services, agreeing that 90 minutes for brake pads is too high and should be standardized to 60 minutes. They debated whether to treat brake pad replacement and rotor replacement as separate services or a combined workflow, with Abdelrahman Hamdy Akl (Abdul) emphasizing that rotors and pads are almost always replaced

together to avoid cross-contamination. The team acknowledged that while a rotor replacement can sometimes occur alone in exceptional circumstances, the standard, more efficient practice is to combine the two procedures.

Pick service options
Each option-based service needs a pick before booking.

Brake Pad Replacement
PICK POSITION

Front \$171 - \$191	Rear \$151 - \$171
Front and rear \$310 - \$350	

Rotor Replacement
PICK POSITION

Front \$344 - \$404	Rear \$314 - \$364
Front and rear \$634 - \$744	

0/2 picked

Cancel Confirm options


meet.google.com is sharing your screen. Stop sharing Hide

Type here to search


Top Stories

1:21 PM
8/24/2026


- **Routine Maintenance Time Estimates:** The participants reviewed times for routine maintenance tasks, such as oil changes and spark plug replacements. Abdelrahman Hamdy Akl (Abdul) suggested that using a decimal-based hour system (e.g., 1.0 hours) is standard industry practice for shops, as it simplifies multiplication for labor rates. They discussed whether car data enrichment—which would allow the system to provide specific, pre-populated times based on the vehicle model—was active, noting that the system does not yet account for the specific vehicle.



- Fuel System Cleaning Procedures:** Abdelrahman Hamdy Akl (Abdul) clarified that in a typical shop setting, a "fuel system cleaning" service usually consists of pouring a bottle of cleaning additive into the fuel system rather than a mechanical deep clean. They discussed charging for the part (which costs approximately \$15) plus 10 minutes of labor, noting that this is a common add-on during oil changes.
- Battery Service and Relearn Procedures:** The group discussed battery load tests and replacements, agreeing that 30 minutes is an appropriate labor time. Abdelrahman Hamdy Akl (Abdul) noted that many modern vehicles require a battery "relearn" procedure after a new battery is installed to ensure all dashboard lights function correctly, and suggested this should be a separate labor line or explicitly included in the service. Yassin Wahman noted that if the vehicle data is enriched, the system should ideally account for this specific relearn procedure.
- Pre-Purchase Inspection Standards:** Abdelrahman Hamdy Akl (Abdul) confirmed that 105 minutes is a fair labor estimate for a pre-purchase inspection. They described the process as a combination of a diagnostic scan and a physical inspection, where the mechanic removes wheels, measures components, and performs a comprehensive check.



- **VIN Input and System Enrichment Issues:** The participants investigated why the vehicle VIN input was not triggering a "confirm vehicle" popup, which is required to start the data enrichment process. Developer setup explained that the system relies on this popup to trigger the automatic population of vehicle-specific information and parts, and suggested that if the initial input fails, the user might need to recreate the booking.




- Service Catalog Expansion:** Abdelrahman Hamdy Akl (Abdul) identified gaps in the service catalog, specifically for common tasks like bulb replacements and wiper blade replacements. The team agreed these should be added to the catalog, with the system saving these custom services for future use by the shop and others.
- Parts Catalog and Manual Input:** The participants addressed the inability to add parts from a catalog due to the lack of vehicle data enrichment. Yassin Wahman and developer setup clarified that the booking flow being tested is for shop "self-reporting" rather than the customer-facing app flow, which would normally handle confirmation and payment holds. Abdelrahman Hamdy Akl (Abdul) began manually entering part details to proceed with the test booking.
- Scheduling and VIN Character Troubleshooting:** The team encountered an error when trying to book a job because the VIN contained an "O" instead of a "0," which resulted in invalid character errors. They also noted that the booking end time was automatically calculating based on the shop's closing hours, which needed verification.
- API Credits and Financial Tracking:** During the session, the system experienced failures in vehicle data enrichment, which developer setup

attributed to the exhaustion of cloud API credits. Developer setup mentioned that they had recently spent approximately \$500 across various platforms due to high usage volume and manually refilled the credits to resolve the failure.


- **Parts Management and Sourcing Links:** Abdelrahman Hamdy Akl (Abdul) continued to manually add parts and included links to parts sources, such as FCP Euro, to help the team build their catalog database. Developer setup noted that they implemented a feature allowing mechanics to save these sources, which helps the system gather information for future use.
- **Fluid Specifications and OEM Standards:** The group discussed the complexities of fluid requirements, with Abdelrahman Hamdy Akl (Abdul) noting that modern vehicles, especially those newer than 2020, require very specific certifications. They decided that while OEM numbers are good references, they should be careful not to present pricing that seems exorbitant (e.g., \$111 per quart for genuine Audi fluid) if compatible, high-quality aftermarket fluids (like ZF or Fuchs) with the same certifications are available for significantly less.
- **User Interface Layout Concerns:** Abdelrahman Hamdy Akl (Abdul) noted that the interface felt cramped on a 16-inch laptop screen, making it difficult to see multiple fields at once. Developer setup acknowledged that the UI needs to be adjusted for different screen sizes, as the current layout requires users to minimize or collapse fields frequently to maintain visibility.
- **Booking Submission and User Feedback:** After finalizing the inputs, including manual part entries and adjustments, the booking was submitted. Reflecting on the process, Abdelrahman Hamdy Akl (Abdul) noted that while the system is effective, the user experience of having data fields auto-populate and change while the user is typing—coupled with the screen space issues—was slightly frustrating, though manageable with practice.
- **Quote Submission Process:** The meeting concluded with Yassin Wahman and Abdelrahman Hamdy Akl (Abdul) beginning the process of submitting a tire quote for a Ford Mustang. They discussed using the scheduling interface to select an available time slot and assigning a mechanic to the task.
- **Tire Categorization Logic:** The team discussed the need to categorize tire brands into tiers (premium, mid-tier, and low-tier) to ensure customers receive appropriate recommendations and to prevent shops from misleading customers by substituting generic, low-quality tires for premium ones. Yassin

Wahman argued that the system should restrict the list to specific, reputable brands based on the chosen category, while the developer setup noted that while they previously attempted systemic classification, the vast catalog made this difficult.


- **Implementation of Tiered Tire Lists:** Yassin Wahman confirmed they possess an existing list that classifies tire brands into tiers. It was decided that they would implement this restriction, with Yassin Wahman committing to send this list to the developer setup for system integration. Abdul successfully tested a quote for Pirelli tires, including labor costs and estimated duration, to verify the updated quote system flow.
- **Booking System UI and Logic Issues:** During the booking process, the team identified a flaw where the system prevented the selection of a specific time slot (2:30 PM) because the system erroneously flagged it as already being held. Daniel C clarified that this was a known issue where the interface failed to recognize that the current user was the one holding the slot. Daniel C committed to updating the booking flow to allow users to either accept the currently held time or choose an alternative slot.
- **Quote and Schedule Syncing:** The group debugged the schedule view to locate pending quotes. The developer setup noted that while they lacked a dedicated system for mechanics to easily review previously submitted quotes, they could view "pending" and "on hold" statuses directly within the schedule interface.




- Integration of "On Hold" Booking Logic:** The team determined that the booking code was not fully integrated with the new "on hold" logic, leading to system errors when attempting to finalize a booking. They discussed that existing booking restrictions, such as the requirement that a booking must be scheduled at least one hour after the current time, were causing conflicts. Yassin Wahman also flagged issues with specific services like differential fluid changes for the M3, which the developer setup acknowledged required further investigation.
- Rotor and Brake Pad Quoting:** Regarding a Porsche brake job involving rotors and pads, the team discussed that rotor quotes must explicitly include pads, as they cannot be replaced independently. Yassin Wahman emphasized that since quotes are sent to multiple shops, the "on hold" functionality must not unnecessarily block service slots. They established that quotes should be set to expire after approximately 10 minutes.




- Importance of Vehicle Data and Specs:** Abdul expressed the necessity of having vehicle identification numbers and detailed car specifications to provide accurate quotes, as generic model designations (such as "911") led to incorrect parts selection. The team confirmed that for specific vehicles, such as the Porsche 911 Turbo S, they must rely on precise original equipment manufacturer information to avoid incorrect fitment.




- Aftermarket Parts Challenges:** Abdul highlighted the difficulty of sourcing aftermarket parts for high-performance vehicles like the Turbo S with ceramic brakes, noting that rotors can cost up to 10,000 dollars each. Yassin Wahman noted that many shops would likely decline such complex jobs, but they agreed to use the system to explore available alternatives.



- Functionality of the "Other" Category:** The team identified a bug where the "other" selection category for parts, such as rotors or pre-inspection items, was not functioning correctly within the quote system. Yassin Wahman confirmed that this was a persistent issue that required resolution, as it prevented users from progressing through the selection process.
- Scheduling Conflicts and Booking UI:** The team encountered multiple issues with scheduling, including quotes being applied to the wrong vehicles and incorrect date assignments. Yassin Wahman observed a conflict where a brake job for a Mustang was incorrectly linked to a quote for a Turbo S. The developer setup agreed to investigate these backend configuration errors.



- Pre-Job Menu and Specs Verification:** Yassin Wahman tested the pre-job menu by adding an Audi and verifying that the system successfully retrieved accurate mileage and service requirements, such as a brake fluid flush, which Abdul confirmed was an accurate recommendation for the vehicle's state.




- Pricing Transparency and Service Inclusion:** The team reviewed the quote details for a multi-service job including tires, an oil change, and a brake fluid

flush. Abdul noted that the pricing, specifically 479 dollars, was competitive and transparent for a professional-grade service compared to standard shop practices. They identified a UI issue where the list of included services was not immediately visible to the user without scrolling.


- **Vehicle Check-In and Inspection Flow:** Abdul and Yassin Wahman tested the check-in process, where the system pre-filled specifications based on vehicle records. They noted that the requirement to scroll to reach the "specs match" button created a suboptimal user experience. Daniel C suggested that saving these specifications server-side would ensure consistency if the page refreshed.

The screenshot shows a web browser window with multiple tabs. The active tab is titled "Otopair" and shows a URL: "https://repairconnect-web-git-temurdev-temur-3996s-projects.vercel.app/schedule". The main content is a "Multi-point inspection" form. The form has a title bar with "Multi-point inspection" and "First visit". Below the title bar, it says "Yassin Wahman · Brake Fluid Flush, Tire Rotation, Oil Change · Today, 2:50 PM". There is a button labeled "Owner profile" with a "3 skipped" indicator. The form is divided into several sections: "Owner profile" (with a sub-header "OPTIONAL" and a note "Questions the customer skipped during onboarding. Fill in what you can observe or ask."), "When was the last service?" (with radio button options: "< 1 month", "1-3 months", "3-6 months", "6-12 months", "12+ months", "Not sure"), "What was done at the last service?" (with checkboxes: "Oil change", "Brakes", "Tires", "Battery", "Inspection", "Other", "None"), "What's this vehicle's role?" (with radio button options: "Primary / daily", "Weekend / secondary", "Stored / seasonal", "Shared / family"), and "Aftermarket modifications" (with a checkbox). There is a "Mark zone complete" button. At the bottom of the form, there are three buttons: "Verify a measurement with a photo -> rating boost", "Save & close", and "Submit -> Vehicle Health". The browser's address bar shows the URL, and the taskbar at the bottom shows various application icons and the system clock (2:56 PM, 8/24/2026).


- **Canceling and Reassigning Bookings:** The team worked to cancel erroneous bookings and reassign services. They discovered that the interface made it difficult to cancel specific jobs, as clicking on a booking often redirected users to the quote section rather than providing a dedicated cancellation sheet.



- "Any Mechanic" Assignment Logic:** Daniel C identified a logic flaw where bookings assigned to "any mechanic" were effectively locked to a specific mechanic (Abdul) instead of allowing lateral movement. Daniel C committed to fixing the system so that when a customer selects "any mechanic," the booking can be moved to another technician without requiring manual rescheduling and customer re-confirmation.




- UI Improvements for Navigation:** The team discussed UI improvements for the vehicle specifications verification section. Abdul and Daniel C agreed that the "specs match" button should be a floating element that remains visible regardless of the user's scroll position. Yassin Wahman suggested implementing a navigation system similar to DocuSign, using highlighted indicators that jump users to specific sections, which would reduce the need for continuous scrolling.




- UI Improvements for Save Functionality:** The team discussed an issue where the save button position caused visual jumping. To resolve this, they agreed to keep the UI stationary by moving the saved status indicator to the left side and replacing the text with a simple checkmark.
- Brake Fluid Level Logic:** Daniel C explained that the back-end logic for brake fluid levels relies on comparing current measurements to previous ones to identify potential brake pad wear rather than focusing on static markings. Abdelrahman Hamdy Akl (Abdul) and the team confirmed that the existing five-tier grading system is sufficient for these inspections.
- Reducing Ambiguity in Brake Fluid Levels:** To prevent confusion between "Max" and "High" levels, which Abdelrahman Hamdy Akl (Abdul) identified as potentially redundant, the team discussed whether to refine the terminology.

They concluded that while the five-tier system is effective, adding visual guidance would help clarify the readings for technicians.


- **Implementation of Educational Information Icons:** To clarify brake fluid levels without adding unnecessary clutter, Daniel C proposed adding an information icon ("i") that, when clicked, displays a diagram explaining the different levels (Max, High, Mid, Low, Min). Abdelrahman Hamdy Akl (Abdul) noted that these visual cues make the software feel professional and helpful for technicians.




- **Horn Inspection Protocol:** Abdelrahman Hamdy Akl (Abdul) emphasized the importance of the horn in safety inspections, noting that a non-functional horn results in an automatic failure during New York State inspections. The team agreed to keep the horn inspection as a mandatory part of the vehicle check.



- **Horn Repair Diagnosis Workflow:** The team established a two-stage process for horn issues, starting with a diagnostic period (15 to 20 minutes) to identify whether the problem is the fuse, clock spring, or the horn component itself. Once the diagnosis is complete, the repair can be approved.
- **Multi-point Inspection Submission Bug:** Daniel C identified a bug where clicking "Add to this job" during the multi-point inspection immediately submits the entire inspection, preventing the mechanic from finishing the rest of the checks. The team identified this as a critical item to fix.



- Transmission Fluid Service Recommendation Logic:** Yassin Wahman and Daniel C reviewed the transmission fluid service recommendation flow. They noted inconsistencies in whether the recommendation appears and agreed to investigate whether these suggestions rely on vehicle enrichment or catalog status.



- **Tire Inspection Features:** The team confirmed that fields for tire brand, size, and type are currently not required. Abdelrahman Hamdy Akl (Abdul) noted that keeping these options available is useful for those who wish to input the data.
- **Copying Inspection Data Between Wheels:** Abdelrahman Hamdy Akl (Abdul) and Yassin Wahman discussed the "copy" feature for inspection data, which allows a mechanic to mirror the state of one wheel to others. They emphasized that this should only be performed after the full inspection for that wheel is complete.
- **Handling Missing Brake Measurements:** Daniel C confirmed that mechanics have the option to mark a measurement as "not visible" if they cannot access the brake pad thickness. The team noted a minor bug where entering a number and then selecting "not visible" kept both inputs, and agreed this should be resolved so the number disappears.
- **Brake Rotor Thickness Data Collection:** The team discussed the difficulty of relying on rotor stamp text for measurements, as it is often faded or inaccessible due to rust and dirt. Daniel C noted that the current reliance on this text for determining minimum thickness is not accurate for every vehicle.

The screenshot displays a web browser window with a 'Multi-point inspection' form. The form is titled 'Front-left corner' and includes several input fields with dropdown menus and checkboxes. The 'Outer brake pad thickness' field is set to '7 mm' with a 'Good' status. The 'Pad measurement method' is 'Brake lining gauge'. 'Applicable rotor present' is 'Yes'. 'Brake rotor thickness' is '0.984 in' with a reference of 'min 0.906 in' and an 'In spec' status. The 'Rotor measurement tool' is 'Micrometer'. 'Exact rotor-stamp text' is 'F U'. 'Brake rotor surface issues' includes options like 'none', 'scored', 'pitted', 'rusted', 'warped', and 'grooved'. 'Caliper slides / boots' and 'Brake hose condition' are also present. A 'Copy to FR' button is located at the top right of the form. The background shows a Google Meet window with participants Daniel C and Abdelrahman Hamdy Akl (Abdul). The browser address bar shows 'https://repairconnect-web-git-temurdev-temur-3996s-projects.vercel.app/schedule'.


- **Rotor Minimum Thickness Calculation:** Yassin Wahman proposed using a 15% wear threshold subtracted from the original rotor thickness specification to determine the minimum viable thickness. Abdelrahman Hamdy Akl (Abdul)

agreed that this is an effective method for identifying when rotors are no longer viable.


- **Distinguishing Pre-check from Multi-point Inspection Workflows:** The team discussed the difference between a pre-check (visual walkaround with a flashlight) and a multi-point inspection (in-depth measurements requiring tools like micrometers). They agreed that the pre-check should focus on items that do not require tools, while the multi-point inspection should occur when the vehicle is on the lift.

The screenshot displays a web application interface for a 'Multi-point inspection'. The main form is titled 'Front-left corner' and is divided into several sections. The 'Run-flat tire' section has a 'Yes' dropdown and a 'Saved' status. The 'Tire type' section has an 'All-Season' dropdown and a 'Saved' status. The 'BRAKES - VISUAL' section includes a 'Brake visual state' with a green indicator and a 'Saved' status. The 'BRAKES - WHEEL OFF' section is highlighted and contains the following fields: 'Inner brake pad thickness' (auto-classified), 'Outer brake pad thickness' (7 mm, Good), 'Pad measurement method' (Brake lining gauge), and 'Applicable rotor present' (Yes). The 'Brake rotor thickness' field shows a value of 0.984 in, which is 'In spec'. The form also includes a 'Verify a measurement with a photo' button and a 'Submit --> Vehicle Health' button. The background shows a 'Schedule' view and a Google Meet window with participants Daniel C. and developer satu.


- **Workflow Adjustment for Technician Efficiency:** Abdelrahman Hamdy Akl (Abdul) suggested that the detailed multi-point inspection should be triggered once the mechanic begins work to ensure they are getting paid for the time spent taking measurements. The team agreed this would increase professionalism and efficiency.
- **Aligning Inspection Tasks with Physical Workspace:** The team agreed that the workflow should differentiate between tasks performed on the ground and those performed once the vehicle is on the lift. Detailed measurements like rotor thickness will be grouped into the portion of the job where the vehicle is lifted.



- Multi-point Inspection Trigger Timing:** Yassin Wahman suggested that for jobs requiring brake services, a pop-up should appear when the technician clicks "Start Job," directing them to the relevant inspection page. This ensures the necessary data is collected before the technician's hands become too greasy to use the device.
- Evaluating the Requirement for Rotor Stamp Photos:** After discussing the impracticality of relying on physical stamp text for rotor thickness, the team decided to eliminate the requirement for a photo of the rotor stamp. Abdelrahman Hamdy Akl (Abdul) confirmed that technicians rarely look for these stamps.



- OEM Brake Rotor Specification Sourcing:** The team agreed to source the Original Equipment Manufacturer rotor specifications from external data sources rather than requiring the technician to find them on the vehicle. This simplifies the inspection process for the mechanic.



- Brake Rotor Wear Thresholds:** Abdelrahman Hamdy Akl (Abdul) explained that rotor thickness exceeding a 15% wear threshold is dangerous due to poor

thermal dissipation and spongy braking. The team confirmed this 85% remaining thickness threshold as the standard for replacement.

- **Addressing Quoting and Brake Part Discrepancies:** The team identified a need to reconcile inconsistencies where the booking drawer requests genuine manufacturer parts while the quoting system asks for aftermarket brands like Brembo. They also noted that pad and rotor replacements should be combined into a single job to accurately reflect labor time.
- **Quote System Revamp Responsibility:** Daniel C accepted responsibility for revamping the quote system. The team agreed that they will meet later in the week to finalize how to integrate brake pads and rotor replacements into a single, cohesive workflow.
- **Pull Request Status and Timer Logic Updates:** The developer reported that the custom job and pre-check flow are functioning and that they have addressed the timer logic. Specifically, the timer now pauses when the inspection pop-up appears and resumes automatically once the user closes it.
- **Document Sharing and Status:** developer setup requested that Yassin Wahman provide specific notes, including the tire notes, if they had not already been submitted. Yassin Wahman confirmed that they would provide the tire notes and also finalize the language regarding how to address missing parts with users.
- **Communication Regarding Missing Pricing:** Yassin Wahman and developer setup discussed the need to develop clear language to inform users about missing information, specifically regarding pricing for "Jaws". The participants agreed that it is important to proactively communicate to users that they should expect a price increase. They confirmed that this communication strategy is specifically intended for the application side.
- **Future Meeting Coordination:** The participants concluded the meeting and confirmed that they have another meeting scheduled in three hours. Daniel C noted that they need to record a movie in the interim before the next meeting, and the group expressed hope that they have sufficient time to complete the task.

You should review Gemini's notes to make sure they're accurate. [Get tips and learn how Gemini takes notes](#)

How is the quality of **these specific notes**? [Take a short survey](#) to let us know your feedback, including how helpful the notes were for your needs.