

Appendix A. Test Photos

Report No.: FR3O0803

SPORTON INTERNATIONAL INC. Page No. : 1 of 6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973





1 Photographs of Conducted Emissions Test Configuration



Report No.: FR3O0803

FRONT VIEW



Page No.

Report Version

: 2 of 6

: Rev. 01

REAR VIEW

SPORTON INTERNATIONAL INC.
TEL: 886-3-327-3456

FAX: 886-3-327-0973



FCC Test Report No.: FR3O0803



SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : 3 of 6
TEL: 886-3-327-3456 Report Version : Rev. 01


FAX: 886-3-327-0973





2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



Report No.: FR3O0803

FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 4 of 6
Report Version : Rev. 01




FCC Test Report No.: FR3O0803

For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW


 ${\tt SPORTON\ INTERNATIONAL\ INC.}$

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 5 of 6
Report Version : Rev. 01




FCC Test Report No.: FR3O0803

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : 6 of 6
Report Version : Rev. 01