Extruder Bearing Hinge - WA-110-S

Steps 3 and 4

Remove the remaining material where shown.

