

Testing & C	ommissioni	ng Re	port ICL L	JPS System 1st Floor		
Project Team	Project Manager Architect Electrical Consultant	ASPL H3 Eleken As	sociates	Civil & ID Electrical		
	('ontractor			☐ Mechanical / Plumbing		
WORI	K PERFORMED	ASPL H3 Eleken Associates TOTAL Construction (SM Engineering) SYSTEM CONDITION SYSTEM CONDITION SYSTEM IS WORKING OK SYSTEM HANDED OVER SYSTEM HANDED OVER SYSTEM HANDED OVER YES No. RUNNING CONDITION A UPS for ICL Building install at 1st floor IT room has been Connected, ming and handover to client rep. COMMISSIONED Muhammad Nadir Muhammad Nadir Site Supervisor				
WIRING	6	L-				
INSTALLATION		Der .	SYSTEM IS WORKING OK YES No.			
CALIBRATION	W	bu	BATTERY ALARM YES No.			
COMMISSIONIN	SYSTEM HANDED OVER YES No. RUNNING CONDITION YES No.					
TROUBLE SHOO	BLE SHOOT RUNNING CONDITION VES No.					
	LIER V OKVA UPS for ICI	Building		or IT room has been Connected,		
TESTED TROUBLE SHOOT						
Signature of Con	ACT!		The second secon			
Witness by Project Manager	Name		Date	Signature		
Approved by Electrical Consultant	Name		Date	Signature		







SILICON TECHNOLOGIES support@silicon.net.pk (021-34537287)

		T#9472				
Sr.No 41	669	Field Serv	ice Report UPS	PM	Date & Time: <u>26</u>	1-2022
Customer Name: S	tandard i	Chartered	Bank Cf	& S.M.E	Location: Ko	rachi
		deriger			Tel No:0319	1-2056957
JPS Detail:		0			(mo	· Shahaaib)
Model No ITA-20/		OKVA	Incident No 94	72 Ser	rial No 21012017	4022003001
62Pe	00					
nout Voltage: 403	34405V.406	Frequency:	SOHZ	Earth Pitch Cond	ition:	
		Frequency:				
put Circuit Breaker:_	32/	tub.	Output C	ircuit Breaker:3	2 Amp	
nput Cable Size:	10 m	m yore _AVR: -	Output (Cable Size: 10 Kg	my hos	2
urrent Load:	· –	AVR:	Room Temperat	ure: Normal	Neutral to Earth V	oltage:
Reported Fault:						
PC Reset	O/Load	No Main sense	Out of order	Less Backup Time	Low Batt	Burning smell
Noise on Backup	Others					
Diagnose Fault:						
lugilos runto		Boards	Battery	Others	Client Site	
Buzzer	AC Filter Capacitor	AVR .	Batt Discharged	Plug Loose	Main Disconnected	Overload by Client
Fan Faulty	Relay Problem	Display Problem	Batt Faulty	Plug Burned	I/P Voltage Low<170	PC Supply Faulty
Short		Main Sensing	Batt Terminal Loose	Socket Loose	I/P Voltage High<270	UPS Switch Off
Fuse Open		Chg Amp Low	Batt Unbalance	Socket Burned	Lives Neutral Short	Stabilizer
Micro Controller		No Charging		P/Cord Burned	O/P Vol High (UPS)	
Power Mosfet		No Backup		O/P Socket Burned		
Inv Txrf Problem		Dry Sold Connection		Charger Faulty		
epair Action:			and the			
Faulty Parts Replace	Board Replace	Fuse Replace	Recalibrate System	Batt Recharged	Batt Replace	Service
arts Description	1:	. MAY				- , ,
Parts	2 20	Kar.	Parts '			
]Qty			Qty			
ngineer Name:	Faroog	Khan.	Engineer	Dispatched Date &	Time: 06-11-2	622,11:00
b Start	04:30	m	Job Finishe	d 08 %	oopm	
gr. Recommenda	tion / Remarks_C	ytomer S	ite visited	, New UP	25 Installo	tion has
Been Don	e UPS V	Nooking N	opmal Bo	th Mode	s Are of	(, Baltery
		by custon		1	. 1	-
ustomers Commer		.0			00	
	,	8		GINE		-
lame & Signature (c	customer):	HELD				
ustomer Satisfactio	n: Excellent	Good Unsatisfied	di	SI SIV		
ue copy for Customer			Pink Copy RMA	MAIN	Y	ellow Copy for Engineer