
PAINTSHOP 1 — WORK STATION LAYOUT

PLAN VIEW (TOP) · NOT TO SCALE · MATERIAL FLOW: RIGHT → LEFT



STAGE-WISE MANPOWER & WORK DESCRIPTION (read right → left, following material flow)

4 COVERING & PALLETING	3 OTHER ACCESSORY FITTING	2 UNLOADING	1 DEFECT RECTIFICATION
Manpower: 1 (Man-4)	**Manpower: 1 (Man-3)**	**Manpower: 1 (Man-2)**	**Manpower: 1 (Man-1)**
After ensuring all assembly and quality inspection, cylinder to be unloaded and palletized.	Grease application on masked unpainted area, cap end dust seal assembly.	Rod eye end dust seal fitment and unloading from conveyor.	Demasking and defect scuffing and correction.