

Assignee is Aravindh K Status = Done

P1921 - Clutch paddle flickering - new PCBA

Closed Done

Closed Done

Closed Done

Closed Done

Closed Done

Closed Done

Closed Done

Closed Done

Closed Done

Closed Done

Closed Done

Ghost button input reported by driver UI when pressing one of the 2-way-rocker-switches UP on the BME

corsair-gaming/endor-ag/endor-ee/issue-reporter/tracker#683

◇ Sustaining bugfix Iteration 2

Bosch

Field Issue

FW

P1920A (CS DD)

Test

Fix approval [Pass]

ToDo

Done

 priority

high

Closed

✓ Done

Handbrake input is jumping & flickering on the CSDD/+

corsair-gaming/endor-ag/endor-ee/issue-reporter/tracker#674

◇ v464 Driver Version (Handbrake issu...

P2008 (CS HB V2)

Release

Approved

Test

Fix approval [Pass]

ToDo

Done

 priority

critical

 release

v464-Handbrake-V2

 reproducible

yes

 rootcause

unknown

Closed

✓ Done

Big deadzone on CSL P (without LC) connected to CS DD

corsair-gaming/endor-ag/endor-ee/issue-reporter/tracker#660

◇ Sustaining bugfix iteration 1

P1920A (CS DD)

Release

Release Candidate

Test

Fix approval [Pass]

ToDo

Done

 priority

high

 reproducible

yes

 rootcause

known

Closed

✓ Done

ACP blocks Pedal functionality. (Xbox) (CSDD 2.1.0.2)

corsair-gaming/endor-ag/endor-ee/issue-reporter/tracker#648

◇ Sustaining bugfix iteration 1

📅 No start date – Oct 15, 2024

McL V2

P1920A (CS DD)

RForm V2 Release

Release Candidate

ToDo

Done

Xbox

 priority

high

 rootcause

unknown

Closed

✓ Done

CS DD+ boots in PS5 mode after shutting down in PS4 mode

corsair-gaming/endor-ag/endor-ee/issue-reporter/tracker#638

◇ Sustaining bugfix iteration 1

P1920A (CS DD)

Release

Release Candidate

Test

Fix approval [Pass]

ToDo

Done

 priority

low

 reproducible

yes

Closed

✓ Done

[FEATURE] BMR Tuning Menu adjustment by holding DPad up/down not working

corsair-gaming/endor-ag/endor-ee/issue-reporter/tracker#572

◇ Sustaining bugfix iteration 1

P1921 (GT SW X)

P2101 (P BMR)

Release

Release Candidate

Test

Fix approval [Pass]

ToDo

Done

 priority

low

Closed

✓ Done

BMR entering a Tuning Menu setting or leaving it by pushing Dpad is not working (Only P DD and CSL DD)

corsair-gaming/endor-ag/endor-ee/issue-reporter/tracker#569

◇ Sustaining bugfix iteration 1

P1921 (GT SW X)

P2101 (P BMR)

Release

Release Candidate

Test

Fix approval [Pass]

ToDo

Done

 priority

low

Closed

✓ Done

Secondary shifter inputs missing on APMs on HUBs

corsair-gaming/endor-ag/endor-ee/issue-reporter/tracker#675

◇ Sustaining bugfix Iteration 3

📅 No start date – Jul 25, 2025

Bosch

Field Issue

FW

P1904A (CSL DD)

P1904B (GT DD Pro)

P1920A (CS DD)

P1920B (CS DD+)

ToDo

Open

UH(X) V2

 priority

critical

 reproducible

yes

Closed

✓ Done

Button LED wheels often boot with not all Constant Color Button LEDs lighting

corsair-gaming/endor-ag/endor-ee/issue-reporter/tracker#723

◇ Sustaining bugfix Iteration 3

📅 No start date – Sep 17, 2025

P1703 (P SW BMW GT3/GT4)

P1920A-(CS-DD)

P1920B-(CS-DD+)

P1921-(GT-SW-X)

Closed

✓ Done