

Quality Inspection Summary

Scrap Rate: 4.3%

Rework Rate: 7.9%

Several product batches rejected due to dimensional tolerance issues.

Operators report difficulty maintaining process stability.