

# Service Training and Quality Parameters mapped on Dashboard

- 1. Technician Strength
- 2. Experience Profile
- 3. Star Rating
- 4. Training Mandays
- 5. CSAT Survey Reports
- 6. PRA
- 7. FTF
- 8. Spare Replaced
- 9. Monthly Repeat
- 10. Annual Repeat


#### 1. Technician Strength




#### 2. Technician Experience Profile




#### 3. Star Rating




#### 4. Mandays



#### 5. CSAT Survey Report




#### 6.1 PRA Status




Branch can easily monitor PRA limit consumed, Proportion of Damage vs Defective and Refund Indication

#### 6.1.1 PRA Status




With Cross-linked Visualizations, branch can better analyse replacement data with insights of refund indication and damage vs defective as a sub-division

#### 11. Monthly Repeat




Monthly Repeat Performance can be monitored and analysed for Normal and RDC calls in One Page.

#### 12.1 Annual Repeat – Zone and Branch Wise



### 12.3 Annual Repeat – Technician Wise




### 12.4 Annual Repeat – Technician Wise - Call Details

	Franchisee Id	Installation	Job Category 1	Job Category 2	Job Category 3	Service Order Number	Technician Id	Branch	Zone Repeat Cou	unt RPT
	3HX000702	RD052141501SD01417-190701417dr01121	LIGHT BULB / LED	LIGHT BULB/LED FUSED	SPARES REPLACED	178474	804943	MUMBAI	West	2
	3HX000702	RD052141501SD01417-190701417dr01121	THERMOSTAT	KNOB - SETTING INCORRECT	CUSTOMER EDUCATION	102410	804943	MUMBAI	West	2
	3HX000702	RD052141501SD01430-181201430DR01499	LIGHT BULB / LED	BULB/LED COVER BROKEN	REFITTED	152999	804943	MUMBAI	West	1
	3HX000702	RD052141501SD01433-190101433DR01979	MAIN DOOR	GASKET DISLOCATED	REFITTED	142032	804943	MUMBAI	West	1
	3HX000702	RD052141501SD01439-181101439DR00355	THERMOSTAT	EXCESS COOLING	SPARE REPLACED	105709	804943	MUMBAI	West	1
	3HX000702	RD052141501SD01634-190301634DR01685	LOOSE CONNECTION	BULB HOLDER	REFITTED	115800	804943	MUMBAI	West	1
	3HX000702	RD052141501SD01634-190601634dr05487	WATER LEAKAGE/SWEATING	SWEATING - MAIN DOOR	REFITTED	152264	804943	MUMBAI	West	2
	3HX000702	RD052141501SD01640-190501640DR15593	MAIN DOOR	GASKET GAP	REFITTED	218410	804943	MUMBAI	West	1
	3HX000702	RD0521415015D01640-190801640DR01374	CABINET	LEVELLING DONE	LEVELLING DONE	171199	804943	MUMBAI	West	1
	3HX000702	RD0521415015D01640-191001640DR03303	CABINET	APRON / FRONT FACIA (NON MUT) BROKEN - IN TRANSIT	SPARE REPLACED	180849	804943	MUMBAI	West	2
	3HX000702	RD0521415015D01641-190701641DR08346	FREEZER DOOR	LOCK BRACKET - BROKEN	SPARE REPLACED	212943	804943	MUMBAI	West	1
	3HX000702	RD0521415015D01644-191101644DR00842	MAIN DOOR	GASKET GAP	REFITTED	229964	804943	MUMBAI	West	1
	3HX000702	RD0521415015D01655-190801655dr00289	LIGHT BULB / LED	LIGHT BULB/LED FUSED	SPARES REPLACED	113138	804943	MUMBAI	West	1
		00264	THERMOSTAT	EXCESS COOLING	SPARE REPLACED	171031	804943	MUMBAI	West	1
Landing Page for Drill through		CONTROL CARD	MAIN PCB - PCB ERRATIC MAIN PCB	SPARE REPLACED	255294	804943	MUMBAI	West	2	
_	_	01102	FREEZER DOOR	DOOR - DAMAGED/DENTS & SCRATCHES	SPARE REPLACED	214608	804943	MUMBAI	West	1
Technician Wise.		FREEZER DOOR	DOOR - DAMAGED/DENTS & SCRATCHES	SPARE REPLACED	258204	804943	MUMBAI	West	2	
	0	3336	MAIN DOOR	DOOR - MISALIGNED IN-TRANSIT	ADJUSTED - REFITTED	228040	804943	MUMBAI	West	2
	3HX000702	RD052141501SD02001-200902001DR00591	LIGHT BULB / LED	LIGHT BULB/LED FUSED	SPARES REPLACED	228526	804943	MUMBAI	West	1
	3HX000702	RD052141501SD02006-200702006DR00005	LIGHT BULB / LED	LIGHT BULB/LED HOLDER DEFECTIVE	REFITTED	203171	804943	MUMBAI	West	1
	3HX000702	RF02N0D-190100402FR00731	DEFROST TIMER (FF MANUAL)	STICKY NOT WORKING	SPARE REPLACED	126662	804943	MUMBAI	West	2
	21 21 21 22 22 22	0.0000000000000000000000000000000000000	Sensor	NOT WORKING	SPARE REPLACED	117759	804943	MUMBAI	West	2
This will help branch to analyse cause of repeat and			MAIN DOOR	DOOR - MISALIGNED IN-TRANSIT	ADJUSTED - REFITTED	183563	804943	MUMBAI		1
				STICKY NOT WORKING	SPARE REPLACED	135163	804943	MUMBAI	West	1
			DEFROST TIMER (FF MANUAL)	STICKY NOT WORKING	SPARE REPLACED	229102	804943	MUMBAI		1
allalyse	cause	or repeat and	MAIN DOOR	DOOR - MISALIGNED IN-TRANSIT	ADJUSTED - REFITTED	173807	804943	MUMBAI		1
iron out issues			AIR FLOW (MULTI FLOW DUCT)		REFITTED	187108	804943	MUMBAI		1
HOH OUL ISSUES		AIR FLOW (MULTI FLOW DUCT)		REFITTED/REMOVED	114773	804943	MUMBAI	West	1	
		THE SECTION ASSESSMENT OF THE SECTION ASSESS	DEFROST TIMER (FF MANUAL)	STICKY NOT WORKING	SPARE REPLACED	239211	804943	MUMBAI		1
	3HX000702	RF02NYQ-191200373FR00215	MAIN DOOR	GASKET GAP	REFITTED	182217	804943	MUMBAI		1
	3HX000702	RF02NYZ-190900412FR00146	COMPRESSOR	NOISE - RUNNING - ABNORMAL	CUSTOMER CONVINCED	216846	804943	MUMBAI		1
	3HX000702	RF02NZZ-190300406FR00327		MULTI FLOW DUCT MISALGINED	REFITTED / ADDED FOAM		804943	MUMBAI		2
	3HX000702	RF02NZZ-190300406FR00327	THERMOSTAT	EXCESS COOLING	SPARE REPLACED	214908	804943	MUMBAI		2
:	3HX000702	RF02NZZ-190900406FR00332		NO AIR FLOW THRU DUCT (FF)	REFITTED/REMOVED	173924	804943	MUMBAI		2
	3HX000702	RF02NZZ-190900406FR00332	THERMOSTAT	EXCESS COOLING	SPARE REPLACED	215030	804943	MUMBAI		2
	3HX000702	RF052141501SD01363-190601363FR01170	DEFROST TIMER (FF MANUAL)		SPARE REPLACED	207075	804943	MUMBAI		2
	21 2022 2022	RF052141501SD01476-190301476FR01569	MAIN DOOR	GASKET GAP	REFITTED	203763	804943	MUMBAI		1
	3HX000702		MAIN DOOR	DOOR - MISALIGNED IN-TRANSIT	ADJUSTED - REFITTED	113960	804943	MUMBAI		1
	3HX000702	RF052141501SD01556-190901556FR00010								
	3HX000702 3HX000702	RF052141501SD01556-191101556fr00204	MAIN DOOR	DOOR - HINGE BEND	REALIGNED	242905	804943	MUMBAI		2
	3HX000702			DOOR - HINGE BEND DOOR - MISALIGNED IN-TRANSIT NOISE - RUNNING - ARNORMAL	REALIGNED  ADJUSTED - REFITTED  CUSTOMER CONVINCED	242905 247068 173741	804943 804943 804943	MUMBAI MUMBAI MUMBAI	West	2

Internal


#### Unique things about this dashboard

#### Recognition of Month as per Financial Year




Power BI sorts month as per Calendar year. Logic developed to sort the same as per Financial Year

### Multiple cross report and those visualization linkages enabling useful insights




## Manual data cleansing and calculation steps are mapped in Power Query



This helps avoid redundancy of the same upon updation

### Filters at Dax Level instead of usual Visual or Page Level



This allows to free other variables of the calculation from these filters thereby allowing complex calculation automated. In absence of this many manual steps may have been added rendering the updation of parameter cumbersome and time taking.

# Last Source File Updation Date displayed on Dashboard Page

