

Service Training and Quality Parameters mapped on Dashboard

- 1. Technician Strength
- 2. Experience Profile
- 3. Star Rating
- 4. Training Mandays
- 5. CSAT Survey Reports
- 6. PRA
- 7. FTF
- 8. Spare Replaced
- 9. Monthly Repeat
- 10. Annual Repeat


1. Technician Strength




2. Technician Experience Profile




3. Star Rating




4. Mandays



5. CSAT Survey Report




6.1 PRA Status




Branch can easily monitor PRA limit consumed, Proportion of Damage vs Defective and Refund Indication

6.1.1 PRA Status




With Cross-linked Visualizations, branch can better analyse replacement data with insights of refund indication and damage vs defective as a sub-division

6.2 PRA Status Age wise




Ageing Wise PRA data helps branch review product performance and conduct failure analysis

7. First Time Fix




First Time Fix data visualization is directly linked to OLAP database and can provide real time data on a single refresh.

7.1 First Time Fix




With Product category, Zonal and Quarter wise Slicers Zonal data can be easily analysed for a particular quarter or product category.

8. Spare Replaced




Spare Consumption data can be analysed Zone wise, Quarter Wise, Month Wise as well as for a particular ASP

11. Monthly Repeat




Monthly Repeat Performance can be monitored and analysed for Normal and RDC calls in One Page.


12.1 Annual Repeat – Zone and Branch Wise



12.2 Annual Repeat – ASP Wise



12.3 Annual Repeat – Technician Wise




12.4 Annual Repeat – Technician Wise - Call Details

	⊕			12M REPEAT R DETA	ILS					
1	Franchisee Id	Installation	Job Category 1	Job Category 2	Job Category 3	Service Order Number	Technician Id	Branch	Zone Rep	eat Count RPT IN
	3HX000702	RD052141501SD01417-190701417dr01121	LIGHT BULB / LED	LIGHT BULB/LED FUSED	SPARES REPLACED	178474	804943	MUMBAI	West	2
1	3HX000702	RD052141501SD01417-190701417dr01121	THERMOSTAT	KNOB - SETTING INCORRECT	CUSTOMER EDUCATION	102410	804943	MUMBAI	West	2
1	3HX000702	RD052141501SD01430-181201430DR01499	LIGHT BULB / LED	BULB/LED COVER BROKEN	REFITTED	152999	804943	MUMBAI	West	1
1	3HX000702	RD052141501SD01433-190101433DR01979	MAIN DOOR	GASKET DISLOCATED	REFITTED	142032	804943	MUMBAI	West	1
1	3HX000702	RD052141501SD01439-181101439DR00355	THERMOSTAT	EXCESS COOLING	SPARE REPLACED	105709	804943	MUMBAI	West	1
	3HX000702	RD052141501SD01634-190301634DR01685	LOOSE CONNECTION	BULB HOLDER	REFITTED	115800	804943	MUMBAI	West	1
1	3HX000702	RD052141501SD01634-190601634dr05487	WATER LEAKAGE/SWEATING	SWEATING - MAIN DOOR	REFITTED	152264	804943	MUMBAI	West	2
1	3HX000702	RD052141501SD01640-190501640DR15593	MAIN DOOR	GASKET GAP	REFITTED	218410	804943	MUMBAI	West	1
1	3HX000702	RD052141501SD01640-190801640DR01374	CABINET	LEVELLING DONE	LEVELLING DONE	171199	804943	MUMBAI	West	1
1	3HX000702	RD052141501SD01640-191001640DR03303	CABINET	APRON / FRONT FACIA (NON MUT) BROKEN - IN TRANSIT	SPARE REPLACED	180849	804943	MUMBAI	West	2
	3HX000702	RD052141501SD01641-190701641DR08346	FREEZER DOOR	LOCK BRACKET - BROKEN	SPARE REPLACED	212943	804943	MUMBAI	West	1
1	3HX000702	RD052141501SD01644-191101644DR00842	MAIN DOOR	GASKET GAP	REFITTED	229964	804943	MUMBAI	West	1
1	3HX000702	RD052141501SD01655-190801655dr00289	LIGHT BULB / LED	LIGHT BULB/LED FUSED	SPARES REPLACED	113138	804943	MUMBAI	West	1
	_	00264	THERMOSTAT	EXCESS COOLING	SPARE REPLACED	171031	804943	MUMBAI	West	1
Landing P	age to	or Drill through 19903	CONTROL CARD	MAIN PCB - PCB ERRATIC MAIN PCB	SPARE REPLACED	255294	804943	MUMBAI	West	2
•		01102	FREEZER DOOR	DOOR - DAMAGED/DENTS & SCRATCHES	SPARE REPLACED	214608	804943	MUMBAI	West	1
Tec	Technician Wise.		FREEZER DOOR	DOOR - DAMAGED/DENTS & SCRATCHES	SPARE REPLACED	258204	804943	MUMBAI	West	2
		3336	MAIN DOOR	DOOR - MISALIGNED IN-TRANSIT	ADJUSTED - REFITTED	228040	804943	MUMBAI	West	2
1	3HX000702	RD052141501SD02001-200902001DR00591	LIGHT BULB / LED	LIGHT BULB/LED FUSED	SPARES REPLACED	228526	804943	MUMBAI	West	1
	3HX000702	RD052141501SD02006-200702006DR00005	LIGHT BULB / LED	LIGHT BULB/LED HOLDER DEFECTIVE	REFITTED	203171	804943	MUMBAI	West	1
1	3HX000702	RF02N0D-190100402FR00731	DEFROST TIMER (FF MANUAL)	STICKY NOT WORKING	SPARE REPLACED	126662	804943	MUMBAI	West	2
,	21.01000702	Product descent	Sensor	NOT WORKING	SPARE REPLACED	117759	804943	MUMBAI	West	2
This w	This will help branch to			DOOR - MISALIGNED IN-TRANSIT	ADJUSTED - REFITTED	183563	804943	MUMBAI	West	1
11113 VV	This will help branch to		DEFROST TIMER (FF MANUAL)	STICKY NOT WORKING	SPARE REPLACED	135163	804943	MUMBAI	West	1
analyse	analyse cause of repeat and			STICKY NOT WORKING	SPARE REPLACED	229102	804943	MUMBAI	West	1
allalyse C	Lause	or repeat and	MAIN DOOR	DOOR - MISALIGNED IN-TRANSIT	ADJUSTED - REFITTED	173807	804943	MUMBAI	West	1
ire	iron out issues		AIR FLOW (MULTI FLOW DUCT)	VEGETBLE GETTING SPOILED	REFITTED	187108	804943	MUMBAI	West	1
IIC				NO AIR FLOW THRU DUCT (FF)	REFITTED/REMOVED	114773	804943	MUMBAI	West	1
2		THE PROPERTY OF THE PROPERTY O	DEFROST TIMER (FF MANUAL)		SPARE REPLACED	239211	804943	MUMBAI	West	1
1	3HX000702	RF02NYQ-191200373FR00215	MAIN DOOR	GASKET GAP	REFITTED	182217	804943	MUMBAI		1
1	3HX000702	RF02NYZ-190900412FR00146	COMPRESSOR	NOISE - RUNNING - ABNORMAL	CUSTOMER CONVINCED	216846	804943	MUMBAI		1
1	3HX000702	RF02NZZ-190300406FR00327		MULTI FLOW DUCT MISALGINED	REFITTED / ADDED FOAM		804943	MUMBAI		2
1	3HX000702	RF02NZZ-190300406FR00327	THERMOSTAT	EXCESS COOLING	SPARE REPLACED	214908	804943	MUMBAI	West	2
1	3HX000702	RF02NZZ-190900406FR00332		NO AIR FLOW THRU DUCT (FF)	REFITTED/REMOVED	173924	804943	MUMBAI		2
1	3HX000702	RF02NZZ-190900406FR00332	THERMOSTAT	EXCESS COOLING	SPARE REPLACED	215030	804943	MUMBAI	West	2
1	3HX000702	RF052141501SD01363-190601363FR01170	DEFROST TIMER (FF MANUAL)		SPARE REPLACED	207075	804943	MUMBAI		2
1	3HX000702	RF052141501SD01476-190301476FR01569	MAIN DOOR	GASKET GAP	REFITTED	203763	804943	MUMBAI		1
1	3HX000702	RF052141501SD01556-190901556FR00010	MAIN DOOR	DOOR - MISALIGNED IN-TRANSIT	ADJUSTED - REFITTED	113960	804943	MUMBAI		1
1	3HX000702	RF052141501SD01556-191101556fr00204	MAIN DOOR	DOOR - HINGE BEND	REALIGNED	242905	804943	MUMBAI		2
1	3HX000702	RF052141501SD01556-191101556fr00204	MAIN DOOR	DOOR - MISALIGNED IN-TRANSIT	ADJUSTED - REFITTED	247068	804943	MUMBAI		2
1	Total	RE0521415015D01556-191201556ER00186	COMPRESSOR	NOISE - RUNNING - ARNORMAL	CUSTOMER CONVINCED	173741	804943	MUMBAI	West	169
3	lotal									109


Unique things about this dashboard

Recognition of Month as per Financial Year




Power BI sorts month as per Calendar year. Logic developed to sort the same as per Financial Year

Multiple cross report and cross visualization linkages enabling useful insights




Manual data cleansing and calculation steps are mapped in Power Query



This helps avoid redundancy of the same upon updation

Filters at Dax Level instead of usual Visual or Page Level



This allows to free other variables of the calculation from these filters thereby allowing complex calculation automated. In absence of this many manual steps may have been added rendering the updation of parameter cumbersome and time taking.

Last Source File Updation Date displayed on Dashboard Page

