

Description	Service Charge
1 meter copper pipe set (with insulation, wire)	₹ 874
AC fan blade	₹ 680
AC install	₹ 1,747
AC Service Lite (split)	₹ 601
AC Service Lite (window)	₹ 436
AC uninstall	₹ 484
Anti-rust deep clean AC service	₹ 1,018
Anti-rust Spray (Avoid gas leak)	₹ 242
Blower motor - Split AC	₹ 2,136
Blower replaced	₹ 1,068
Capillary and filter replaced	₹ 340
Combo Capacitor (Comp+Fan)	₹ 485
Comp Capacitor - 25 to 60 mfd	₹ 388
Compressor 0.8-1 ton	₹ 6,311
Compressor 1.5 ton	₹ 7,282
Compressor 2 ton	₹ 8,932
Compressor grommets set	₹ 290
Connector wires replaced (1m)	₹ 97
Contactora Daikin/ O-General	₹ 1,456
Contactora replaced	₹ 485
Convert PCB with remote	₹ 1,456
Copper Coil Condensor 1 ton Split	₹ 3,398
Copper Coil Condensor 1.5 ton Split	₹ 3,883
Copper Coil Condensor 2 ton Split	₹ 4,369
Copper Cooling Coil (Split AC)	₹ 5,825
Copper Cooling Coil (Split AC) - 1 Ton	₹ 4,854
Copper Cooling Coil (Split AC) - 1.5 Ton	₹ 5,825
Copper Cooling Coil (Split AC) - 2 Ton	₹ 6,796
Copper Cooling Coil (Split AC) O General & Mitshubishi - 1.5 Ton	₹ 6,796
Copper Cooling Coil/Condensor Coil (Window AC)	₹ 4,369
Copper Cooling Coil/Condensor Coil (Window AC) - 1 Ton	₹ 3,883
Copper Cooling Coil/Condensor Coil (Window AC) - 2 Ton	₹ 4,854
Copper Cooling Coil/Condensor Coil(Window AC) - 1.5 Ton	₹ 4,369
Expansion valve replaced	₹ 1,165
Fan Capacitor - 2.5 to 10 mfd	₹ 243

Description	Service Charge
Fan motor - Split AC	₹ 1,748
Fan motor - Window AC	₹ 2,524
Fastner complete set	₹ 194
Flair nut replaced	₹ 146
Floor stand	₹ 534
Fuse Change in PCB	₹ 146
Gas Charging	₹ 2,621
Grill Cover	₹ 1,456
Indoor unit reinstalled	₹ 679
Inverter PCB repaired	₹ 3,883
Motor Bearing Change	₹ 971
Non-Inverter PCB repaired	₹ 1,748
Outdoor unit reinstalled	₹ 776
Power Saver AC service (split)	₹ 582
Power Saver AC service (window)	₹ 533
Replace Flap/Swing Motor	₹ 388
Replace sensor	₹ 340
Replacement Compressor (1 Ton)	₹ 3,883
Replacement Compressor (1.5 Ton)	₹ 4,369
Replacement Compressor (2 Ton)	₹ 4,854
Service valve replaced - 1/2	₹ 388
Service valve replaced - 1/4	₹ 388
Service valve replaced - 5/8	₹ 485
Sleeves (per piece)	₹ 49
Split AC Wall stand	₹ 728
Stabilizer repair	₹ 1,456
Swing blade replaced	₹ 388
Tighten/ Replace Thimble	₹ 49
Universal back plate	₹ 291
Universal remote	₹ 777
Water Leakage Repaired- Split AC	₹ 97
Water tray	₹ 485