

Release Notes for AT32A423 Firmware Library Drivers

V2.0.4-2026/06/02

1. PWC
 - `__force_stores()` is replaced with the `__ISB()` and `__DSB()` to adapt to different compilers
2. CRM
 - Updated the processes of the `crm_reset()`, the `crm_hick_sclk_frequency_select()` and the `crm_hick_divider_select()` to avoid possible clock failure during switching
3. EXINT
 - Added a new `EXINT_TRIGGER_NONE_EDGE` for software tripper without edge configuration requirements
4. Updated some notes

V2.0.3-2025/11/24

5. ADC
 - Removed unnecessary bit name "`spt_bit.cspt18`" and the register definition "`csts_bit`"
6. CRM
 - Changed the bit name from `adc14rst` to `tmr14rst`
 - Removed unnecessary `CRM_xxx_PERIPH_LOWPOWER` definitions
7. TMR
 - Updated these functions: `tmr_pwm_input_config()`, `tmr_encoder_mode_config()` and `tmr_output_channel_config()`.
The channel must be disabled before configuring channel mode, otherwise it fails to switch between channel modes
8. Updated some notes

V2.0.2-2025/01/20

1. Updated LDO output level settings.

V2.0.1-2024/12/13

1. Updated CAN driver.
2. Updated USB driver.
3. Updated PWR driver.
4. Updated some notes.

V2.0.0-2023/03/24

1. Initial release of AT32A423 firmware library drivers.