




SPIRIT

www.makecnc.com



Assembly steps:

STEP 1



STEP 2



STEP 3



STEP 4




STEP 5




STEP 6



ENGRAVING —




Step 1



Note: Use glue for better stability of the 3d model.




Step 2






Step 3




Note: Use glue for better stability of the 3d model.





ASSEMBLY STEPS

Page 6 of 9




Step 4






Step 5

Note: Use glue for better stability of the 3d model.




ASSEMBLY STEPS

Page 8 of 9



Step 6

Note: Use glue for better stability of the 3d model.



ASSEMBLY STEPS

Page 9 of 9

