

POST-SERVICE COMPLETION REPORT

Reference: SR-1764133049850298

BASIC INFORMATION

Priority:	NORMAL
Status:	COMPLETED
Created Date:	26/11/2025, 10:27:29 am

ISSUE DESCRIPTION

temperature required

Error Code: e45

Ø<ßâ Company Name: Crystal Group
Ø=Üþ Onsite Contact: 9876543210
Ø=ÜÍ Site Address: Goregaon West, Mumbai

& þ Preferred Technician Call: Thu, 27 Nov

CLIENT DETAILS

Company:	Hetero Labs Ltd - unit 3 (EOU)
Contact:	Hetero Labs Ltd - unit 3 (EOU)
Phone:	+000735978025
Address:	Jeedimetla

CONTAINER DETAILS

Code:	CXRU1326276
Type:	refrigerated
Location:	Oakland

ASSIGNED TECHNICIAN

No technician assigned

REQUIRED PARTS

1. SZ-N75-3000 sensor (Subzero) [5 mtr long] (2)
2. Asian Apcolite Black Paint 1 Ltr (1)
3. YAK Quick Drying Enamel Oxford Blue (2)
4. YARK Synthetic Black 1 Ltr (2)
5. Acetone (1)

WORK PERFORMED

done

CONFIDENTIAL - This document contains proprietary information

