

EHS CRITICAL PRECURSOR AUDIT REPORT #NM-2026-104

Department: Heavy Fabrication & Stamping

Location: Bay 7 - Stamping Press Die Staging Area

Equipment Involved: 20-Ton Overhead Demag Bridge Crane #3

Reporter Role: Rigging Specialist & Safety Marshal

Immediate Action Taken: Crane tagged out (LOTO Red Tag #441), die secured on timber cribbing

Incident Description and Narrative:

During lifting operations of a 14-ton automotive stamping die, the hoist wire rope exhibited severe bird-caging and two parted outer wire strands. While suspended at 8 feet over an unbarricaded transit aisle, the primary hoist drum brake slipped 4 inches before catching. Workers standing 10 feet away heard grinding. Drop netting was missing and ground exclusion zone had not been roped off.

Investigation Findings and Safeguard Assessment:

Physical inspection confirms barrier defect and procedural violation. Immediate review of lockout/tagout and secondary containment is mandated before resuming operations.