

Maintenance Work Order Logs

****Unit:** 4 Cooling Loop**

WO_ID	Date	Equipment	Issue	Action Taken
5510	2025-04-10	Pump P-204	High vibration	P-204 bearing replaced — 1st occurrence this year.
5518	2025-08-05	Pump P-204	Overheating	P-204 bearing replaced — 2nd occurrence this year. Grease found degraded.
5521	2025-12-02	Pump P-204	Seized	P-204 bearing replaced — 3rd occurrence this year. Housing cleaned and inspected.