DESIGN AND DEVELOPMENT OF CONTINUOUS POSITIVE AIRWAY PRESSURE USING SMART-PHONE

A PROJECT REPORT

Submitted by

ANANDHI RAGHURAMAN ASMITHA A

in partial fulfillment for the award of the degree

of

BACHELOR OF ENGINEERING

in

ELECTRONICS AND INSTRUMENTATION ENGINEERING

EASWARI ENGINEERING COLLEGE

ANNA UNIVERSITY: CHENNAI 600 025

MAY 2021

ANNA UNIVERSITY: CHENNAI 600 025

BONAFIDE CERTIFICATE

Certified that this project report "DESIGN AND DEVELOPMENT OF CONTINUOUS POSITIVE AIRWAY PRESSURE USING SMART-PHONE" is the bonafide work of "ANANDHI RAGHURAMAN and ASMITHA A" who carried out the project work under my supervision.

SIGNATURE SIGNATURE

DR. S. NAGARAJAN MR. T. SURENDRAN

HEAD OF THE DEPARTMENT SUPERVISOR

Assistant Professor,

Department of Electronics and Department of Electronics and

Instrumentation Engineering, Instrumentation Engineering,

Easwari Engineering College, Easwari Engineering College,

Ramapuram, Chennai-89. Ramapuram, Chennai-89.

Appendices:

```
#include <LiquidCrystal.h>
#include <SoftwareSerial.h>
#include "DHT.h"
LiquidCrystal lcd(12, 11, 10, 9, 8, 7);
SoftwareSerial blue_tx_rx (2, 3);
define ard node blue tx rx
#define splash splash1
#define DHTTYPE DHT11
#define resp A0
#define DHTPIN A1
#define ky1 4
#define ky2 5
#define compres 6
DHT dht(DHTPIN, DHTTYPE);
int a, b;
int H B, SPO 2;
int hum;
float temp;
String IncomingData = "";
String outB = "";
String modefn = "";
int res r, resfn;
int res r t = 700;
float res tim = 0.0;
```

```
int C Status;
int C tim = 10;
float cc tim = C tim;
int k1 r, k2_r;
int C auto;
int DispDelay;
void setup() {
 // put your setup code here, to run once:
 Serial.begin(115200);
 blue tx rx.begin(9600);
 dht.begin();
 pinMode(resp, INPUT);
 pinMode(ky1, INPUT PULLUP);
 pinMode(ky2, INPUT PULLUP);
 pinMode(compres, OUTPUT);
 digitalWrite(compres, LOW);
 LcDSet();
 lcd.clear();
}
void LcDSet() {
 lcd.begin(16, 2);
 // Print a message to the LCD.
 lcd.clear();
 splash(0, "CPAP");
 splash(1, "MACHINE");
 delay(1000);
```

```
void loop() {
 setDisp();
 getArd();
 getDht();
 k1 r = digitalRead(ky1);
 k2 r = digitalRead(ky2);
 if (k1 r == 0 \text{ and } C \text{ auto} == 0) {
  splash(1, "Auto Mode OFF");
  delay(100);
  C auto = 1;
 }
 else if (k1 r == 0 \text{ and } C \text{ auto} == 1) {
  splash(1, "Auto Mode ON");
  resfn = 0;
  res tim = 0;
  delay(100);
  C auto = 0;
 }
 if (C auto == 0) {
  getres();
  outB = "T : ";
  outB += String(temp);
  outB += " H : ";
  outB += String(hum);
   outB += "% HB : ";
  outB += String(H B);
  outB += " SPO2 : ";
  outB += String(SPO 2);
  outB += "% R:";
  outB += String(resfn);
```

```
outB += " || ";
 outB += " Mode : ";
 outB += "Auto ";
 outB += " || ";
 outB += "Compressor Status = ";
 if (C Status == 1) {
  digitalWrite(compres, HIGH);
  outB += "ON";
 Else
  digitalWrite(compres, LOW);
  outB += "OFF";
else {
 if (k2 r == 0 \text{ and } C \text{ Status} == 0) {
       digitalWrite(led, HIGH);
  splash(1, "C ON");
  delay(100);
  C Status = 1;
 else if (k2_r == 0 \text{ and } C_S \text{tatus} == 1) {
  splash(1, "C OFF");
       digitalWrite(led, LOW);
  lcd.setCursor(0, 0);
  lcd.print("
                               ");
  delay(100);
  C Status = 0;
 outB = "T : ";
```

```
outB += String(temp);
 outB += " H : ";
 outB += String(hum);
 outB += "% HB : ";
 outB += String(H B);
 outB += " SPO2 : ";
 outB += String(SPO 2);
 outB += "% R : ";
 outB += String(resfn);
 outB += " || ";
 outB += " Mode : ";
 outB += "Manual ";
 outB += " || ";
 outB += "Compressor Status = ";
 if (C Status == 1) {
  outB += "ON";
 else
  outB += "OFF";
if (C Status == 1) {
 digitalWrite(compres, HIGH);
Else
 digitalWrite(compres, LOW);
Serial.println(outB);
blue tx rx.println(outB);
delay(300);
```

```
void getres()
 res tim += 0.40;
 res r = analogRead(resp);
 Serial.println(res r);
 if (C Status == 0) {
  if (res r > res r t) {
   resfn++;
   splash(0, "Snoring");
   splash(1, "Detected");
 }
 if (res tim > 8 and resfn > 2 and C Status == 0) {
  Serial.println("Comp ON");
  C Status = 1;
  splash(1, "C ON");
  resfn = 0;
  res tim = 0;
 else if (res tim > C tim and C Status == 1) {
  C Status = 0;
  splash(1, "C OFF");
  lcd.setCursor(0, 0);
  lcd.print("
  Serial.println("Comp OFF");
  resfn = 0;
  res tim = 0;
 else if (res tim > 10) {
  C Status = 0;
  Serial.println("Normal");
  resfn = 0;
  res tim = 0;
```

```
}
}
void getArd() {
 String SS = ""; String SSs = "";
 while (ard node.available() > 0) {
  char S = ard node.read();
  SS += S;
  delay(10);
 if (SS.length() > 0) {
  Serial.println(SS);
  String sys = getSplitValue(SS, ',', 0);
  String dia = getSplitValue(SS, ',', 1);
  H B = sys.toInt();
  SPO 2 = dia.toInt();
  ard node.flush();
void getDht() {
 int humidity = dht.readHumidity();
 float temperature = dht.readTemperature();
 /* Serial.print(humidity, 1);
  Serial.print("\t\t");
  Serial.println(temperature, 1);*/
 temp = temperature;
 hum = humidity;
```

```
}
void setDisp() {
 DispDelay++;
 if (DispDelay \geq 0 and DispDelay \leq 15) {
  display ard(H B, SPO 2);
 if (DispDelay \geq 15 and DispDelay \leq 30) {
  display T(temp, hum);
 else if (DispDelay \geq 30) {
  DispDelay = 0;
 if (C Status == 0) {
  lcd.setCursor(0, 1);
  lcd.print("S:
                          ");
  lcd.setCursor(3, 1);
  lcd.print(resfn);
  lcd.setCursor(12, 1);
  lcd.print(res tim);
  cc tim = C tim;
 else if (C Status = 1 and C auto = 1) {
  lcd.setCursor(0, 0);
  lcd.print("Air Flow ON
                                    ");
 else
  lcd.setCursor(0, 0);
  lcd.print("Air Flow ON
                                    ");
  lcd.setCursor(0, 1);
  lcd.print("
                              ");
  lcd.setCursor(12, 1);
  lcd.print(cc tim = 0.38);
```

```
}
void display_ard(int val1 , int val2) {
 lcd.setCursor(0, 0);
                           ");
 lcd.print("HB:
 lcd.setCursor(3, 0);
 lcd.print(val1);
 lcd.setCursor(7, 0);
 lcd.print("SPo2:
                             ");
 lcd.setCursor(12, 0);
 lcd.print(val2);
 lcd.setCursor(15, 0);
 lcd.print("%");
void display T(float val1 , int val2) {
 lcd.setCursor(0, 0);
 lcd.print("T:
                        ");
 lcd.setCursor(3, 0);
 lcd.print(val1, 1);
 lcd.setCursor(8, 0);
                         ");
 lcd.print("H:
 lcd.setCursor(11, 0);
 lcd.print(val2);
 lcd.setCursor(14, 0);
 lcd.print("%");
```

Arduino Code

```
#include <Wire.h>
#include "MAX30100 PulseOximeter.h"
#include <SoftwareSerial.h>
SoftwareSerial and node(2,3);
#define REPORTING PERIOD MS
                                       1000
PulseOximeter pox;
uint32 ttsLastReport = 0;
void onBeatDetected()
 Serial.println("Beat!");
void setup() {
 // put your setup code here, to run once:
 Serial.begin(115200);
 ard node.begin(9600);
 Serial.print("Initializing pulse oximeter..");
 // Initialize the PulseOximeter instance
 // Failures are generally due to an improper I2C wiring, missing power supply
 // or wrong target chip
 if (!pox.begin()) {
  Serial.println("FAILED");
  for (;;);
 } else {
  Serial.println("SUCCESS");
 // The default current for the IR LED is 50mA and it could be changed
 // by uncommenting the following line. Check MAX30100 Registers.h for all
the
```

```
// available options.
// pox.setIRLedCurrent(MAX30100 LED CURR 7 6MA);
 // Register a callback for the beat detection
 pox.setOnBeatDetectedCallback(onBeatDetected);
void loop() {
 // put your main code here, to run repeatedly:
 pox.update();
 // Asynchronously dump heart rate and oxidation levels to the serial
 // For both, a value of 0 means "invalid"
 if (millis() - tsLastReport > REPORTING PERIOD MS) {
  Serial.print("Heart rate:");
  Serial.print(pox.getHeartRate());
  Serial.print("bpm / SpO2:");
  Serial.print(pox.getSpO2());
  Serial.println ("%");
  ard node.print(pox.getHeartRate());
  ard node.print(",");
  ard node.print(pox.getSpO2());
  ard node.print(",");
  tsLastReport = millis();
```