## **TEST REPORT**

**Customer Name:** In-Vitro Fertility Centre, 5<sup>th</sup> Floor

Mother Child Hospital, Beside Gandhi Hospital,

Padma Rao Nagar, Secundrabad, Telangana - 500025

Consignee Name: Asta Infra Projects Pvt. Ltd.,

Sy.No.262/AA, Beside MAK College of Pharmacy, Chilkur Village, Moinabad Mandal, Rangareddy Dist.

501504. T.S

**Model Name:** FXFSQ100ARV16 - 1 No's

FXAQ50ARVE6 – 5 No's FXAQ32ARVE6 – 3 No's FXAQ25ARVE6 – 1 No's

Daikin Air conditioning India Pvt Ltd

K.PichaiManager

**Quality Control Division** 

-078\_km/.

Document No: 2023-09-23-16HP-FERTILITY CENTRE | Issue Date: SEP,23,2023



	Model	Mfg.No.	Model	Mfg.No.	Model	Mfg.No.
	FXFSQ100ARV16	0039522				
	FXAQ50ARVE6	0045392				
	FXAQ50ARVE6	0045305				
	FXAQ50ARVE6	0045299				
	FXAQ50ARVE6	0045373				
TEST REPORT	FXAQ50ARVE6	0045358				
	FXAQ32ARVE6	0032504				
	FXAQ32ARVE6	0032825				
	FXAQ32ARVE6	0032821				
	FXAQ25ARVE6	0013576				
T			G( 1 1			D 14
Inspection Items	Standard					Result
Air tight test	Noleakageat4.3+0.2MPa					Good
Degree of vacuum	Under 5 torr					Good
Resistance insulation	Over $10 \text{ M}\Omega$ by DC $500 \text{ V}$ insulation resistance tester.					Cood
test	(Note)					Good
Voltage withstanding	MustWithstandAC1800V50Hzfor1secondormore.					Good
test	Trust Willistand To 100	70	ondomiore.			0000
	They must operate without abnormal vibration or abnormal noise.					Good
•	Refrigerant pressure and current value must be within the					Good
	tolerance set for each model.					
Earth conductive test	Current25A,Resistancelessthan0.1Ω					Good
Function test for	_					_
operation switch						
•						Good
High pressure operation	essure operation HPS can operate.					
test						
Refrigerant leak test	No leakage shall be found.					Good
	No fault as like scratch, distortion, soiling, gap, unevenness,etc					~ -
External appearance	shall be found.	iatori, arstori	, sommg, <u>s</u>	,ap, and terms	.55,000	Good
visual inspection						
-	They must stick correctly. No error of mentioned item, distortion,					Good
Labels, indications	wrinkle, bubble and peeling shall be found.					
Check of accessories	Specification, number, model name shall be correct.					Good
(Note) This value possibly	•				a.u. vv.la.a.u	

(Note) This value possibly drops caused by accumulation of refrigerant in the compressor, when measuring is executed before or just after installation.

Document No: 2023-09-23-16-FERTILITY CENTRE | Issue Date: Sep,23,2023