ཨཱ།། རབ་བརྟན་འཕྲུལ་ལས་བཟོ་ཁང་།།

RABTEN

ENGINEERING WORKSHOP

AUTOMOBILE ENGINEERS AND FABRICATORS

To

The Regional Manager

Bhutan Postal Corporation Limited

Phuentsholing

Sir,

The estimate for vehicle register number BG2A0975 (jumbo) has been submitted for your approval and we have been provided the work order for half engine overhauling and its total amount is sum of nu 101390.

The above estimate amount has been give through physical inspection of vehicle and after dismantling the engine, we have found out that engine head assy was pitted and worn-out, EGR assy sized and differential pressure sensor fault. In this type of vehicle (BS 4), we were facing engine heating issue, engine oil high consumption and back compressor issue in most of the vehicle (BS 4). We have repaired many vehicles with same issue for other organization too.

In this case we have to replace the engine head assy, because engine head cannot be repaired and EGR assy too. Additional amount will be sum of nu 80104

1. Engine head assy-1nos (55859)
2. EGR ass-1nos- (13304)
3. Differential pressure sensor – 1nos (10941)

Thanks & Regards

Rabten Engineering Workshop

Rabten Engineering Workshop BHUTAN PH : 252238 P.BOX No 258 Phuentsholing

Post Box No. 258, Phuentsholing, Bhutan, Mobile #+975-17160353

E-mail : rewstore@gmail.com, rabtenprs@gmail.com