

Main DDR

Detailed Diagnostic Report

Generated from uploaded inspection and thermal documents/images. The system uses local rules only and does not call any paid AI API. Missing or unclear fields are marked as Not Available.

Input files	Sample Report.pdf, Thermal Images.pdf
Images extracted from PDFs	1927
Client / address	Not Available
Inspection date	Not Available
Generation mode	Local low-credit model

1. Property Issue Summary

The uploaded material indicates property issues related to dampness, leakage, tile joint gaps, plumbing concerns, cracks, or similar inspection findings where such text was available. Exact client, address, and area mapping are kept as Not Available when not found in the uploaded files.


2. Area-wise Observations

1. Parking Ceiling below Flat No. 103

Inspection finding	Leakage observed at parking ceiling below Flat No. 103.
Possible source side	Common Bathroom plumbing issue and tile joint gaps observed.
Reason	possible plumbing leakage; open tile joints or trap area allowing water movement; moisture movement visible in affected area
Thermal reading	Hotspot: 28.8 deg C; Coldspot: 23.4 deg C; Thermal image file: RB02380X.JPGDevice
Source reference	Extracted point 6



Inspection/source image supporting this observation



Thermal/source image supporting this observation

2. Common Bathroom Ceiling, Flat No. 103

Inspection finding	Mild dampness observed at Common Bathroom ceiling.
Possible source side	Gap observed between tile joints of Common and Master Bedroom Bathrooms of Flat No. 203.
Reason	open tile joints or trap area allowing water movement; moisture movement visible in affected area
Thermal reading	Hotspot: 27.4 deg C; Coldspot: 22.4 deg C; Thermal image file: RB02386X.JPGDevice
Source reference	Extracted point 7



Inspection/source image supporting this observation



Thermal/source image supporting this observation

3. Probable Root Cause

Probable root cause is based only on uploaded content. If plumbing leakage, tile joint gaps, Nahani trap issues, or external wall cracks are present in the source, they should be treated as likely contributors. Exact cause: Not Available unless confirmed in the source document.

4. Severity Assessment

Severity is assessed as Moderate when multiple affected areas or repeated leakage/dampness/crack findings are present. If source severity is not explicit, the reasoning is based on count and spread of observations. Exact measured severity: Not Available.

5. Recommended Actions

- Repair confirmed leakage/plumbing source before cosmetic treatment.
- Seal tile joint gaps and inspect bathroom outlet/Nahani trap areas where mentioned.
- Treat damp walls/skirting only after the source has been repaired.
- Repair external cracks or wall openings where observed.
- Re-inspect the same areas after repair and compare with fresh thermal readings if available.

6. Additional Notes

This app is a simple local model. It is designed to reduce credit use by avoiding paid AI calls. For reports with poor scans or unlabeled images, exact image-to-area mapping may remain Not Available.

7. Missing or Unclear Information

- Customer name/contact/address: Not Available
- Exact image-to-area mapping: Not Available when file names or document captions do not identify the area
- Conflicts: Not Available unless contradictory details are detected in extracted text
- Any expected image not uploaded or not extractable: Image Not Available