22

23



delay(1000);



IOTexp12

libraries.txt Library Manager ▼ sketch.ino #include <DHT.h> #define DHTPIN A2 #define DHTTYPE DHT22 DHT dht(DHTPIN, DHTTYPE); void setup() { 8 Serial.begin(115200); 9 dht.begin(); 10 11 12 void loop() { 13 float tempC = dht.readTemperature(); 14 15 if (isnan(tempC)) { 16 Serial.println("Error: Sensor Failure"); 17 18 return; 19 20 21 Serial.println(tempC); // Send data to Serial Plotter













