Supplier Defect Report - FlexFit USB-C Hub 7-in-1: power-delivery and port failures

SDR-2026-027 | Chaudry, Chahal and Sami (S003)

Report ID	SDR-2026-027
Report date	2026-03-18
Supplier	Chaudry, Chahal and Sami (S003)
Supplier contact	supplier3@shopsphere.invalid
Supplier category	accessories
Products	FlexFit USB-C Hub 7-in-1 (P_R101, P_R105, P_R106, P_R109, P_R113)
Batch / lot codes	FF-HUB7-B2601, FF-HUB7-B2602
Severity	Major
Prepared by	Returns Quality Analytics, ShopSphere Retail

1. Summary

Several returns of the FlexFit USB-C Hub 7-in-1 report port or power-delivery failures. Two have inspection-verified defects (R105: PD pass-through does not charge the host and HDMI drops; R106: no HDMI signal). R113 reports dead USB-A ports, but no inspection has been recorded yet, so it is listed for information only and is excluded from defect counts.

2. Return evidence (from ShopSphere order and inspection systems)

Return	Order	Reason	Requested	Inspection	Defect verified
R105	O105	defective	2026-02-25	pass (defective)	Yes
R106	O106	defective	2026-03-02	pass (defective)	Yes
R113	O113	defective	2026-03-10	no inspection on record	-

3. Recurring defect analysis

- Verified failures cluster in the PD pass-through and HDMI paths, which share the hub's DisplayPort-alt-mode and PD controller.
- Failures appear within 2 weeks of first use, which suggests marginal components rather than wear.
- R113 cannot be counted until it has been inspected (evidence gap).

4. Requested supplier actions

- Provide PD controller firmware version and change history for lots FF-HUB7-B2601/B2602.
- Run 72-hour burn-in on 20 retained samples with a 65 W load and share the results.
- Accept return-to-vendor of units with verified defects.

5. Commercial handling

Units with a verified defect are held for return-to-vendor (supplier_return) against the batch codes above. Units with conflicting or missing inspection evidence are excluded from any chargeback until the inspection evidence is complete.