Supplier Defect Report - TechNova Ultrabook 14: unexpected shutdowns and keyboard spares

SDR-2026-029 | Kaul PLC (S005)

Report ID	SDR-2026-029
Report date	2026-03-19
Supplier	Kaul PLC (S005)
Supplier contact	supplier5@shopsphere.invalid
Supplier category	electronics
Products	TechNova Ultrabook 14 (P_R108, P_R112)
Batch / lot codes	TN-UB14-B2512, TN-UB14-B2601
Severity	Major
Prepared by	Returns Quality Analytics, ShopSphere Retail

1. Summary

Return R112 (serial LT8891) has a verified fault: the laptop shuts down unexpectedly and the power-management log shows power-loss events, which points to a mainboard power-rail fault. Return R108 (serial LT2044) has keyboard damage with cracked keycaps and two keys not registering. The damage is repairable by replacing the keyboard/top-case. ShopSphere requests mainboard failure analysis for R112 and keyboard/top-case spares for the R108 repair.

2. Return evidence (from ShopSphere order and inspection systems)

Return	Order	Reason	Requested	Inspection	Defect verified
R112	O112	not_functioning	2026-02-13	pass (defective)	Yes
R108	O108	damaged	2026-03-02	pass (damaged)	Yes

3. Recurring defect analysis

- R112: verified mainboard power fault inside the 24-month warranty; treated as a supplier quality issue.
- R108: physical keyboard damage; not attributed to a manufacturing defect. Listed here only for the spares request.

4. Requested supplier actions

- Accept R112 mainboard for failure analysis; provide a replacement board under warranty.
- Supply 1 keyboard/top-case assembly (TN-UB14 TC-IN layout) for repair task R108.

5. Commercial handling

Units with a verified defect are held for return-to-vendor (supplier_return) against the batch codes above. Units with conflicting or missing inspection evidence are excluded from any chargeback until the inspection evidence is complete.