

myP Bug-Fix Notes 1.4.4

2020-06-04

myP 1.4.4.1

Functionality Fixes

- Fixed a timing issue in PVT movements that was triggered by a collision (behaviours “pause and resume” and “pause and approve”). The issue caused different strange behaviours upon resuming the motion.

Usability Fixes

- Improving an error message that is triggered by a collision (behaviour “stop and release”) to no longer be fading. The user is now aware that a collision occurred.

myP 1.4.4.2

Functionality Fixes

- Store EEPROM robot data redundantly to prevent start-up problems caused by single bit EEPROM errors.
- Improved WiFi performance of host mode.

myP 1.4.4.3

Functionality Fixes

- Fixing a timing issue that caused problems during the P-Rob update.

Contact



F&P Robotics AG
Rohrstrasse 36
CH-8152 Glattbrugg



Phone: +41 44 515 95 20
Fax: +41 44 515 95 25
eMail: info@fp-robotics.com