Incident Report — P-102 Minor Seal Leakage — 2025

Document ID: APEL-INC-2025-017 | Owner: HSE | Revision: 1.8

A minor seal leakage observation was reported during a CDU-4 field round on 18 September 2025.

Facts

Field	Value
Asset	P-102
Unit	CDU-4
Date	18 Sep 2025
Consequence	No injury; no unplanned shutdown

Immediate response

The operator treated the observation as a condition requiring attention.

Actions

- Notify supervisor.
- Check local condition.
- Confirm area safety.
- Request maintenance inspection.
- Increase monitoring.

Investigation

Maintenance found seal degradation consistent with service wear.

Evidence

- Seal-face wear
- Residue around seal chamber
- No casing crack identified
- No major containment failure evidence

Corrective action

The seal assembly was replaced under a controlled work order.

Actions

- Replace seal
- Verify alignment
- Leak check
- Update maintenance history
- Communicate during handover

Learning

The event became part of the asset history used in later reliability review.

Lessons

• Trend seal temperature.

• Capture minor leakage early.

• Link observations to work orders.

• Review recurring seal defects.