PT-102 Calibration and Verification Work Instruction

Document ID: APEL-I&C-331; | Owner: Instrumentation | Revision: 3.3

This page contains the controls and records specific to instrument identity.

Instrument identity

• Tag PT-102

• Range 0–60 bar

• Accuracy ±0.25% span

• Service P-102 discharge pressure

Preparation

This page contains the controls and records specific to preparation.

Preparation

- Verify calibrator ID
- Check calibration status
- Inspect impulse connection
- Record ambient conditions

Calibration points

This page contains the controls and records specific to calibration points.

Calibration points

- 0%
- 25%
- 50%
- 75%
- 100% of range

Acceptance record

This page contains the controls and records specific to acceptance record.

Acceptance record

- As-found value
- Reference value
- Error
- As-left value
- Technician
- Reviewer

Return to service

This page contains the controls and records specific to return to service.

Return to service

- Restore connection
- Leak check
- Verify DCS indication
- Record certificate
- Notify engineering of consequential discrepancy