
GLD-235-12, PIR intrusion detector

1.Introduction

GLD-235-12 is a type of digital & microprocessor-control PIR detector. With pet-immunity function. It adopt precise columnar Fresnel lens to increase the efficiency of energy receiving to achieve high sensitivity without false alarm. With high sensitivity during the detection distance: 0.5m(1.8feet) to 12m (40feet). Advanced pet-immunity function. This detector adopt temperature compensation technology, can recognize the temperature of the environment and compensate IR signal accurately. Fit for indoor



2.Parameter

Input voltage: 9-15VDC Current: 12V@9mA Optical (figure3) Lens data

Curtain beams.: 9+5

Max coverage: 12×12M (40×40 feet) /90°

Alarm tamper


Alarm output: Solid state relay,

N.C, 30mA/30V.

2~3s after alarm the circuit opens. Alarm status: LED light on for 2-3s. Tamper contact: N.C, 50mA/30V



Top view



Side view

Installation:

Surface mount or corner mount, the height 1.8-2.4M from the ground.

Note: Base allow single-side corner mount at 45° to

Or run parallel to the wall.

Bracket to choose:

Wall mount rotation bracket: down 30°, left-right 45°.

Enviroment:

Work temperature: -10°C-50°C (14°F-122°F)

Storage temperature: -20°C-60°C (-4°F-140°F) Anti-RFI: more than 20V/m (20MHz-1000 MHz)

Appearance


Size $(L\times W\times H)$: $94.5\times 63.5\times 49.0$ mm

(3-11/16×2-1/2×1-15/16")

Weight: about 100g

3.Installation

3.1 Attentions



Do not face moving


Do not install outdoor


Do not face the sun


Do not install near high Do not face metal-wall


Do not install on loose-basement


3.2 Installation














8. Customer Service

Our products are very reliable, but for some special reasons, the working performance will be limited in certain range. We here list some cases as follows:

- 1). The voltage of control panel is not stable;
- ②. Low-voltage of the detector.

For any help please contact with our company and your could visit our website for more information.



Warning: We are not responsible for the problem caused by improper operation by users!