AwanSolveAi

Technician Repair Narrative

Synthetic technician narrative

Field	Value
Claim ID	DEMO-002
Technician	Technician B
Equipment	Excavator

Complaint

Boom drifts downward during hold.

Diagnosis

Performed Main hydraulic pressure.

Cause

Internal boom-cylinder seal bypass

Correction

Resealed boom cylinder. Installed part SK-20491.

Final Note

Repair completed and machine returned to service.

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD