AwanSolveAi

Technician Repair Narrative

Synthetic technician narrative

Field	Value
Claim ID	DEMO-010
Technician	Technician J
Equipment	Generator

Complaint

Generator cranks but does not start.

Diagnosis

Performed Fuel rail pressure.

Cause

Failed fuel pressure sensor

Correction

Replaced fuel pressure sensor. Installed part FPS-2118.

Final Note

Repair completed and machine returned to service.

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD