AwanSolveAi

Technician Repair Narrative

Synthetic technician narrative

Field	Value
Claim ID	DEMO-028
Technician	Technician H
Equipment	Loader

Complaint

Bucket tilt cylinder leaks externally.

Diagnosis

Performed Tilt circuit pressure.

Cause

Tilt cylinder rod seal damaged

Correction

Resealed tilt cylinder. Installed part TSK-950.

Final Note

Repair completed and machine returned to service.

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD