Warranty Repair Claim Summary

AwanSolveAi validation corpus

Field	Value
Claim Number	A-006
Equipment Type	Forklift
Asset Model	F45E
Asset Serial Number	FL-45-7006
Meter Hours	1722
Customer Concern	Truck loses drive intermittently after 20 minutes.
Diagnostic Code	DRV-9
Root Cause	Loose traction controller power terminal
Corrective Action	Repaired and torqued power terminal
Replacement Part	TERM-45
Labor Claimed	2.5 hours

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD