Technician Findings

AwanSolveAi validation corpus

Field	Value
Claim ID	A-009
Technician	Validation Technician

Reported Complaint

Engine hunts at low idle after warm-up.

Test Performed

Fuel rail pressure

Confirmed Cause

Fuel metering actuator sticking

Repair Action

Replaced fuel metering actuator

Installed Part

FMA-67

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD