Technician Findings

AwanSolveAi validation corpus

Field	Value
Claim ID	A-012
Technician	Validation Technician

Reported Complaint

Truck loses drive intermittently after 20 minutes.

Test Performed

Traction bus voltage

Confirmed Cause

Loose traction controller power terminal

Repair Action

Repaired and torqued power terminal

Installed Part

TERM-45

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD