Mechanic Diagnostic Report

AwanSolveAi External Validation Pack V1

Field	Value
Claim Number	EXT-015
Technician	External Validation Technician

Customer Concern

Hydraulic/output performance becomes unstable after sustained operation.

Diagnostic Procedure

Control signal and output stability test

Confirmed Cause

Electrical feedback connector resistance caused unstable control signal.

Corrective Action

Connector repaired, terminals secured, and system retested.

Installed Part

CN-4421

SYNTHETIC EXTERNAL-VALIDATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD