Lift Truck Warranty Claim

AwanSolveAi External Set C

Field	Value
Claim, Work Order, or Invoice No.	EXTC-009
Equipment Type	Forklift Mast
Make & Model	LT-M60
Truck Serial No.	LTM60-1209
Hour Meter Reading	2103
Complete Description of Problem	Intermittent loss of performance occurs after extended operation.
Failure Code	C-88
Parts that Caused the Problem	Control feedback connection developed intermittent resistance.
Solution	Connection repaired, terminals secured, and operation retested.
OEM Part#	PT-8842
Labor Hrs Claimed	3.0 hours
Product Identification# & Serial #	PID-9021
Aux Relief PSI	3000
Volume Gpm	18
Failure Date	2026-09-23
Installation Date	2026-02-01

SYNTHETIC EXTERNAL HOLDOUT DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD