Technician Diagnostic Report

AwanSolveAi External Set C

Field	Value
Claim ID	EXTC-013
Technician	External Set C Technician

Customer Concern

Intermittent loss of performance occurs after extended operation.

Diagnostic Procedure

System operating performance test

Confirmed Cause

Control feedback connection developed intermittent resistance.

Corrective Action

Connection repaired, terminals secured, and operation retested.

Installed Part

PT-8842

SYNTHETIC EXTERNAL HOLDOUT DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD