Warranty Repair Claim Summary

AwanSolveAi validation corpus

Field	Value
Claim Number	A-008
Equipment Type	Loader
Asset Model	WL650
Asset Serial Number	LD-650-7008
Meter Hours	1796
Customer Concern	Lift arms settle after engine shutdown.
Diagnostic Code	HYD-44
Root Cause	Lift valve internal leakage
Corrective Action	Replaced lift control valve
Replacement Part	LCV-650
Labor Claimed	4.0 hours

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD