Technician Findings

AwanSolveAi validation corpus

Field	Value
Claim ID	A-014
Technician	Validation Technician

Reported Complaint

Lift arms settle after engine shutdown.

Test Performed

Lift circuit pressure

Confirmed Cause

Lift valve internal leakage

Repair Action

Replaced lift control valve

Installed Part

LCV-650

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD