

# Analyze the two attached documents as an incident investigation assistant. Reco...

Author: NovaMindd Agent

## Task

Analyze the two attached documents as an incident investigation assistant. Reconstruct the incident, identify procedural deviations, correlate the maintenance history with the incident, distinguish confirmed evidence from inference, identify missing evidence, and recommend corrective actions. Do not assume information that is not present in the documents. Cite the source document for every major conclusion.

- Request ID: be4ecf70-aae8-484a-bd5d-ead1e8d8978b
- Status: completed
- Generated: 2026-10-04 16:21 UTC
- Evidence sources: 12
- Tool calls: 0
- Models used: llava:7b, deepseek-coder:6.7b, llama3.2:3b

## Answer

**\*\*Incident Summary Report\*\***

**\*\*Introduction:\*\*** On [Date], a cooling water pump (P-204) tripped on protective vibration shutdown. This report summarizes the findings of the preliminary post-incident inspection, including procedural deviations, confirmed evidence, inferred information, and recommended corrective actions.

**\*\*Procedural Deviations:\*\***

1. **\*\*Lack of certainty about root cause:\*\*** Document E states that "The information in this report alone is insufficient to determine the confirmed root cause of the incident." (Source: Document E)
2. **\*\*Delayed action on vibration readings:\*\*** In document C, it is stated that "Vibration reading recorded at 4.8 mm/s RMS. Technician note: 'Above normal trend; monitor closely.' Vibration reading recorded at 5.6 mm/s RMS." (Source: Document C) This suggests that the pump's vibrational behavior has been monitored but no specific action was taken based on these readings.
3. **\*\*Deferred inspection:\*\*** The 03 September inspection was deferred without clear documentation of why it was delayed. Document E mentions that "The inspection team did not conclude that bearing wear was the initiating cause of the vibration." (Source: Document E) This could imply that there might have been some delay in addressing potential issues related to the vibration incidents.

**\*\*Confirmed Evidence:\*\***

1. **\*\*Vibration readings:\*\*** Vibration readings at 4.8 mm/s RMS and 5.6 mm/s RMS were recorded in maintenance records, suggesting the pump's vibrational behavior has been monitored. (Source: Document C)
2. **\*\*Elevated bearing temperature:\*\*** The bearing temperature trend noted as "slightly

elevated but stable" suggests that vibration incidents may not be directly related to bearings.  
(Source: Document E)

**\*\*Inferred Information:\*\***

1. **\*\*Potential contributing factors:\*\*** The deferred inspection and delayed action on vibration readings suggest potential contributing factors, such as delayed maintenance or inadequate monitoring. 2. **\*\*Vibrational behavior changes:\*\*** The observed vibrational behavior changes over time, suggesting that the pump's condition may have deteriorated.

**\*\*Missing Evidence:\*\***

1. **\*\*Detailed vibration spectrum/frequency-domain analysis:\*\*** This data is necessary to understand the vibrational behavior of the pump before and during the incident. (Source: Document E) 2.

**\*\*Exact time and content of process-area communication:\*\*** Understanding why the process area requested additional cooling capacity is crucial to identifying potential contributing factors. 3.

**\*\*Documented risk assessment:\*\*** Reviewing the documented risk assessment explaining why 03 September inspection was deferred can provide context on potential contributing factors.

**\*\*Recommendations:\*\***

1. Conduct a more comprehensive investigation to gather detailed vibration spectrum/frequency-domain analysis and understand the exact time and content of process-area communication requesting increased cooling capacity. 2. Review and analyze the documented risk assessment explaining why 03 September inspection was deferred to identify potential contributing factors. 3. Implement corrective actions based on the findings, ensuring that all relevant changes are approved by engineering or management personnel before implementation.

**\*\*Action Plan:\*\***

1. Conduct a thorough investigation to gather missing evidence. 2. Analyze and interpret the results of the investigation. 3. Develop and implement corrective actions to prevent similar incidents in the future.

By following this action plan, it is possible to better understand the incident, identify contributing factors, and implement measures to prevent similar incidents from occurring in the future.

## **Reasoning Steps**

### **Step 1 — Document Understanding (Ilava:7b)**

The document describes a preliminary post-incident inspection of a cooling water pump after it tripped on a protective vibration shutdown. The inspection was performed by maintenance personnel and observed several issues, including elevated bearing temperature residue, visible wear at the drive-end bearing housing, coupling guard intactness, and no obvious external shaft damage. The final bearing condition assessment was not completed during this preliminary inspection, and the inspection team did not conclude that bearing wear was the initiating cause of the vibration. Recommended actions include removing and inspecting the drive-end bearing, verifying shaft and coupling alignment, reviewing detailed vibration trend data, and comparing operating conditions before and after the alarm. Engineering sign-off is pending.

## Step 2 — Document\_Understanding (llava:7b)

Document E discusses the missing information in the investigation of the incident involving the cooling water pump. The document identifies three pieces of missing information: the detailed vibration spectrum/frequency-domain analysis, the exact time and content of the process-area communication requesting increased cooling capacity, and the documented risk assessment explaining why the 03 September inspection was deferred. These gaps should be treated as missing evidence and not as evidence that the missing events did or did not occur. The investigation is still ongoing, and mechanical inspection results, maintenance history, and the applicable operating procedure must be reviewed before assigning a root cause. Corrective actions involving equipment replacement, operating-limit changes, or procedure changes require the normal engineering and management-of-change approval process.

## Step 3 — Analysis (deepseek-coder:6.7b)

Based on the provided documents, here are some procedural deviations identified:

1. In document E (Supporting Docs), it is stated that "The information in this report alone is insufficient to determine the confirmed root cause of the incident." This suggests a lack of certainty about the exact cause of the incident. The investigation must be ongoing and more comprehensive data needs to be gathered before assigning a root cause.
2. In document E, it's mentioned that "Corrective actions involving equipment replacement, operating-limit changes or procedure changes require the normal engineering and management-of-change approval process." This implies there might have been some changes made during the incident investigation but they haven't yet been approved by the relevant engineers or management.
3. In document E (Supporting Docs), it is stated that "The vibration reading recorded at 4.8 mm/s RMS. Technician note: 'Above normal trend; monitor closely.' Vibration reading recorded at 5.6 mm/s RMS." This implies the vibrational behavior of the pump has been monitored but there's no specific action taken based on these readings.
4. In document C (Maintenance History), it is stated that "Vibration reading recorded at 4.8 mm/s RMS. Technician note: 'Above normal trend; monitor closely.' Vibration reading recorded at 5.6 mm/s RMS." This implies the vibrational behavior of the pump has been monitored but there's no specific action taken based on these readings.

Correlating maintenance history with the incident, we can see that the cooling water pump had a vibration reading recorded at 4.8 mm/s RMS and 5.6 mm/s RMS in its maintenance records. This could potentially be correlated to the incident as it happened after these readings were made.

Distinguishing confirmed evidence from inference:

1. In document C (Maintenance History), there are several instances where vibration reading was recorded at different levels, suggesting that the pump's vibrational behavior might have been changing over time. This could potentially be inferred to be a contributing factor in the incident.
2. The fact that the bearing temperature trend noted as "slightly elevated but stable" and no bearing replacement recommended suggests that the vibration incidents were not directly related to the bearings, suggesting an inference about the equipment's overall health or condition.

3. In document E (Supporting Docs), it is stated that "The inspection team did not conclude that bearing wear was the initiating cause of the vibration." This could be interpreted as a form of inference, implying that while bearing issues were observed during the inspection, they didn't directly lead to the incident.

4. The fact that the 03 September inspection was deferred suggests there might have been some delay in addressing potential issues related to the vibration incidents. This could be interpreted as a form of inference suggesting post-incident actions were not immediately taken or addressed.

These findings can help guide further investigation and corrective action by engineering or management personnel, ensuring that all relevant changes are approved before implementation.

## **Step 4 — Reasoning (llama3.2:3b)**

Based on the provided documents, here is a reconstructed version of the incident:

### **\*\*Incident Timeline:\*\***

\* 14:08 - P-204 is operating normally at approximately 74% load. \* 14:15 - High-vibration alarm appears for P-204. The operator acknowledges the alarm. \* 14:20 - Alarm acknowledged again after recurrence. No load reduction recorded. \* 14:22 - Vibration alarm temporarily clears. \* 14:25 - Process area requests additional cooling capacity, and P-204's load is increased from approximately 74% to 82%. \* 14:29 - High-vibration alarm returns and remains active. \* 14:32 - P-204 trips on protective vibration shutdown.

### **\*\*Missing Evidence:\*\***

1. Detailed vibration spectrum/frequency-domain analysis: This data could provide more insight into the vibrational behavior of the pump before and during the incident. 2. Exact time and content of process-area communication requesting increased cooling capacity: This information might help understand why the process area requested additional cooling capacity, potentially leading to the incident. 3. Documented risk assessment explaining why 03 September inspection was deferred: This could provide context on why the inspection was delayed, potentially related to addressing potential issues with the vibration incidents.

### **\*\*Inferences and Observations:\*\***

1. The pump's vibrational behavior has been monitored in its maintenance records, with readings at 4.8 mm/s RMS and 5.6 mm/s RMS. 2. The bearing temperature trend noted as "slightly elevated but stable" suggests that the vibration incidents were not directly related to the bearings. 3. The inspection team did not conclude that bearing wear was the initiating cause of the vibration, implying that other factors might be at play.

### **\*\*Procedural Deviations:\*\***

1. Lack of certainty about the confirmed root cause of the incident, suggesting ongoing investigation and data gathering are necessary. 2. Potential for post-incident actions to have been delayed or not immediately addressed, as indicated by the deferred 03 September inspection. 3. Inadequate action taken based on vibration readings in maintenance records, potentially leading to further issues.

### **\*\*Recommendations:\*\***

1. Conduct a more comprehensive investigation to gather detailed vibration spectrum/frequency-domain analysis and understand the exact time and content of process-area communication requesting increased cooling capacity. 2. Review and analyze the documented risk assessment explaining why 03 September inspection was deferred to identify potential contributing factors. 3. Implement corrective actions based on the findings, ensuring that all relevant changes are approved by engineering or management personnel before implementation.

By following these recommendations, it is possible to better understand the incident, identify missing evidence, and implement corrective actions to prevent similar incidents in the future.

## **Step 5 — Text (llama3.2:3b)**

### **\*\*Incident Summary Report\*\***

**\*\*Introduction:\*\*** On [Date], a cooling water pump (P-204) tripped on protective vibration shutdown. This report summarizes the findings of the preliminary post-incident inspection, including procedural deviations, confirmed evidence, inferred information, and recommended corrective actions.

### **\*\*Procedural Deviations:\*\***

1. **\*\*Lack of certainty about root cause:\*\*** The investigation is still ongoing, and more comprehensive data needs to be gathered before assigning a root cause. 2. **\*\*Delayed action on vibration readings:\*\*** Inadequate action was taken based on vibration readings in maintenance records, potentially leading to further issues. 3. **\*\*Deferred inspection:\*\*** The 03 September inspection was deferred without clear documentation of why it was delayed.

### **\*\*Confirmed Evidence:\*\***

1. **\*\*Vibration readings:\*\*** Vibration readings at 4.8 mm/s RMS and 5.6 mm/s RMS were recorded in maintenance records, suggesting the pump's vibrational behavior has been monitored. 2. **\*\*Elevated bearing temperature:\*\*** The bearing temperature trend noted as "slightly elevated but stable" suggests that vibration incidents may not be directly related to bearings.

### **\*\*Inferred Information:\*\***

1. **\*\*Potential contributing factors:\*\*** The deferred inspection and lack of action on vibration readings suggest potential contributing factors, such as delayed maintenance or inadequate monitoring. 2. **\*\*Vibrational behavior changes:\*\*** The observed vibrational behavior changes over time, suggesting that the pump's condition may have deteriorated.

### **\*\*Missing Evidence:\*\***

1. **\*\*Detailed vibration spectrum/frequency-domain analysis:\*\*** This data is necessary to understand the vibrational behavior of the pump before and during the incident. 2. **\*\*Exact time and content of process-area communication:\*\*** Understanding why the process area requested additional cooling capacity is crucial to identifying potential contributing factors. 3. **\*\*Documented risk assessment:\*\*** Reviewing the documented risk assessment explaining why 03 September inspection was deferred can provide context on potential contributing factors.

### **\*\*Recommendations:\*\***

1. Conduct a more comprehensive investigation to gather detailed vibration spectrum/frequency-domain analysis and understand the exact time and content of process-area

communication requesting increased cooling capacity. 2. Review and analyze the documented risk assessment explaining why 03 September inspection was deferred to identify potential contributing factors. 3. Implement corrective actions based on the findings, ensuring that all relevant changes are approved by engineering or management personnel before implementation.

**\*\*Action Plan:\*\***

1. Conduct a thorough investigation to gather missing evidence. 2. Analyze and interpret the results of the investigation. 3. Develop and implement corrective actions to prevent similar incidents in the future.

By following this action plan, it is possible to better understand the incident, identify contributing factors, and implement measures to prevent similar incidents from occurring in the future.

### **Step 6 — Coding (deepseek-coder:6.7b)**

I'm sorry, but your question seems to be missing some context or details. Could you please provide more information about what you need help with? Are you looking for assistance on a specific programming task related to AI, machine learning, data analysis, or another topic? Your current text doesn't seem to contain enough detail for me to provide an accurate response.

## Evidence References

- e0ca9a73a987616c3a8f8381 — Page 3 — Score 6.000
- e0ca9a73a987616c3a8f8381 — Page 2 — Score 5.000
- e0ca9a73a987616c3a8f8381 — Page 1 — Score 4.000
- 7eb8d1b9fd3e7ad523819c00 — Page 3 — Score 3.000
- 7eb8d1b9fd3e7ad523819c00 — Page 2 — Score 2.000
- 7eb8d1b9fd3e7ad523819c00 — Page 1 — Score 1.000
- e0ca9a73a987616c3a8f8381 — Page 3 — Score -1.282
- 7eb8d1b9fd3e7ad523819c00 — Page 3 — Score -1.990
- e0ca9a73a987616c3a8f8381 — Page 2 — Score -5.524
- 7eb8d1b9fd3e7ad523819c00 — Page 2 — Score -7.505
- 7eb8d1b9fd3e7ad523819c00 — Page 1 — Score -7.713
- e0ca9a73a987616c3a8f8381 — Page 1 — Score -8.002