ASHGROVE POINT REEFER YARD
dispatch operations memorandum
operating day AP-2044-D111   day reference DSP-067712

1 RECONCILIATION PASSES

The load reconciliation is worked as a bounded sequence of passes.
The pass budget for this operating day is 5 passes.
The budget is spent whether or not the shares have settled. A pass
that would move a share by less than the minimum step moves it by
the minimum step instead.

pass budget	5
minimum step watt hours	400
dependency protection depth	2

2 DEADLINE SURCHARGE LADDER

A reefer that leaves its mandatory floor unmet at the vessel
cutoff carries a surcharge read off the rung its shortfall reaches,
measured in whole intervals of shortfall.

intervals short	surcharge cents
0	0
1	240
3	610
7	1450

The rung that governs is the highest rung whose interval figure is
at or below the shortfall.

3 CRANE GANG ROSTER

gang	crane	shift	supervisor
gang_a	cr_1	day	supervisor_01
gang_b	cr_2	night	supervisor_02
gang_c	cr_3	relief	supervisor_03
gang_d	cr_4	day	supervisor_04
gang_e	cr_5	night	supervisor_05

4 STANDING NOTES

note 001	the standing reserve of a feeder is withheld before any free capacity is counted
note 002	a crane duty reduces the capacity available to reefers and is not an extra load
note 003	the state of charge may sit on the reserve and nothing may be drawn from it there
note 004	a load equal to the capacity is lawful and is not a violation
note 005	a displaced reefer moves to the next eligible interval and not to the cheapest one
note 006	the pass budget is spent even where the shares are still moving
note 007	the ambient multiplier absent for a class pairing falls back to the class default
note 008	a peak equal to the floor of a demand band belongs to that band
note 009	fd_05 was walked at the shift handover and its cabinet read sealed
note 010	the earth bond of fd_12 was tested at the quarterly inspection

note 011 fd_01 carries a spare contactor in the quay store
note 012 fd_11 is listed on the night office key register
note 013 cr_2 had its rail clamps greased by the maintenance gang
note 014 the load cell of cr_3 was recalibrated last quarter
note 015 cr_4 keeps a laminated plug zone card in its cab
note 016 the agent for vs_lorne asked to be called on arrival
note 017 vs_hesper lodged its manifest with the berth office on time
note 018 vs_hesper is booked against the berth its previous call used
note 019 the switchroom of sb_alder is reached through the north stair
note 020 sb_bourne keeps its single line diagram inside the panel door
note 021 pl_0074 was photographed for the condition file
note 022 the lid gasket of pl_0212 is due for replacement next season
note 023 fd_10 was walked at the shift handover and its cabinet read sealed
note 024 the earth bond of fd_05 was tested at the quarterly inspection
note 025 fd_03 carries a spare contactor in the quay store
note 026 fd_09 is listed on the night office key register
note 027 cr_5 had its rail clamps greased by the maintenance gang
note 028 the load cell of cr_5 was recalibrated last quarter
note 029 cr_2 keeps a laminated plug zone card in its cab
note 030 the agent for vs_fenn asked to be called on arrival
note 031 vs_lorne lodged its manifest with the berth office on time
note 032 vs_cendal is booked against the berth its previous call used
note 033 the switchroom of sb_bourne is reached through the north stair
note 034 sb_calloway keeps its single line diagram inside the panel door
note 035 pl_0156 was photographed for the condition file
note 036 the lid gasket of pl_0040 is due for replacement next season
note 037 fd_14 was walked at the shift handover and its cabinet read sealed
note 038 the earth bond of fd_06 was tested at the quarterly inspection
note 039 fd_04 carries a spare contactor in the quay store
note 040 fd_03 is listed on the night office key register
note 041 cr_3 had its rail clamps greased by the maintenance gang
note 042 the load cell of cr_2 was recalibrated last quarter
note 043 cr_3 keeps a laminated plug zone card in its cab
note 044 the agent for vs_borre asked to be called on arrival
note 045 vs_borre lodged its manifest with the berth office on time
note 046 vs_borre is booked against the berth its previous call used
note 047 the switchroom of sb_calloway is reached through the north stair
note 048 sb_alder keeps its single line diagram inside the panel door
note 049 pl_0136 was photographed for the condition file
note 050 the lid gasket of pl_0209 is due for replacement next season
note 051 fd_08 was walked at the shift handover and its cabinet read sealed
note 052 the earth bond of fd_08 was tested at the quarterly inspection
note 053 fd_09 carries a spare contactor in the quay store
note 054 fd_06 is listed on the night office key register
note 055 cr_1 had its rail clamps greased by the maintenance gang
note 056 the load cell of cr_1 was recalibrated last quarter
note 057 cr_1 keeps a laminated plug zone card in its cab
note 058 the agent for vs_hesper asked to be called on arrival
note 059 vs_durran lodged its manifest with the berth office on time
note 060 vs_durran is booked against the berth its previous call used
note 061 pl_0008 was photographed for the condition file
note 062 the lid gasket of pl_0208 is due for replacement next season

note 063 fd_04 was walked at the shift handover and its cabinet read sealed
note 064 the earth bond of fd_10 was tested at the quarterly inspection
note 065 fd_06 carries a spare contactor in the quay store
note 066 fd_10 is listed on the night office key register
note 067 cr_4 had its rail clamps greased by the maintenance gang
note 068 the load cell of cr_4 was recalibrated last quarter
note 069 cr_5 keeps a laminated plug zone card in its cab
note 070 the agent for vs_durran asked to be called on arrival
note 071 vs_esker lodged its manifest with the berth office on time
note 072 vs_esker is booked against the berth its previous call used
note 073 pl_0015 was photographed for the condition file
note 074 the lid gasket of pl_0185 is due for replacement next season
note 075 fd_02 was walked at the shift handover and its cabinet read sealed
note 076 the earth bond of fd_04 was tested at the quarterly inspection
note 077 fd_12 carries a spare contactor in the quay store
note 078 fd_05 is listed on the night office key register
note 079 the agent for vs_esker asked to be called on arrival
note 080 vs_fenn lodged its manifest with the berth office on time
note 081 vs_fenn is booked against the berth its previous call used
note 082 pl_0163 was photographed for the condition file
note 083 the lid gasket of pl_0016 is due for replacement next season
note 084 fd_13 was walked at the shift handover and its cabinet read sealed
note 085 the earth bond of fd_03 was tested at the quarterly inspection
note 086 fd_13 carries a spare contactor in the quay store
note 087 fd_02 is listed on the night office key register
note 088 the agent for vs_ivell asked to be called on arrival
note 089 vs_cendal lodged its manifest with the berth office on time
note 090 vs_lorne is booked against the berth its previous call used
note 091 pl_0073 was photographed for the condition file
note 092 the lid gasket of pl_0173 is due for replacement next season
note 093 fd_06 was walked at the shift handover and its cabinet read sealed
note 094 the earth bond of fd_13 was tested at the quarterly inspection
note 095 fd_02 carries a spare contactor in the quay store
note 096 fd_04 is listed on the night office key register
note 097 the agent for vs_cendal asked to be called on arrival
note 098 vs_ivell lodged its manifest with the berth office on time
note 099 vs_ivell is booked against the berth its previous call used
note 100 pl_0189 was photographed for the condition file
note 101 the lid gasket of pl_0159 is due for replacement next season
note 102 fd_11 was walked at the shift handover and its cabinet read sealed
note 103 the earth bond of fd_11 was tested at the quarterly inspection
note 104 fd_05 carries a spare contactor in the quay store
note 105 fd_01 is listed on the night office key register
note 106 pl_0066 was photographed for the condition file
note 107 the lid gasket of pl_0181 is due for replacement next season
note 108 fd_01 was walked at the shift handover and its cabinet read sealed
note 109 the earth bond of fd_09 was tested at the quarterly inspection
note 110 fd_14 carries a spare contactor in the quay store
note 111 fd_07 is listed on the night office key register
note 112 pl_0026 was photographed for the condition file
note 113 the lid gasket of pl_0066 is due for replacement next season
note 114 fd_09 was walked at the shift handover and its cabinet read sealed

note 115 the earth bond of fd_07 was tested at the quarterly inspection
note 116 fd_11 carries a spare contactor in the quay store
note 117 fd_12 is listed on the night office key register
note 118 pl_0084 was photographed for the condition file
note 119 the lid gasket of pl_0101 is due for replacement next season
note 120 fd_12 was walked at the shift handover and its cabinet read sealed
note 121 the earth bond of fd_14 was tested at the quarterly inspection
note 122 fd_07 carries a spare contactor in the quay store
note 123 fd_08 is listed on the night office key register
note 124 pl_0094 was photographed for the condition file
note 125 the lid gasket of pl_0206 is due for replacement next season
note 126 fd_03 was walked at the shift handover and its cabinet read sealed
note 127 the earth bond of fd_01 was tested at the quarterly inspection
note 128 fd_08 carries a spare contactor in the quay store
note 129 fd_14 is listed on the night office key register
note 130 pl_0127 was photographed for the condition file
note 131 the lid gasket of pl_0023 is due for replacement next season
note 132 fd_07 was walked at the shift handover and its cabinet read sealed
note 133 the earth bond of fd_02 was tested at the quarterly inspection
note 134 fd_10 carries a spare contactor in the quay store
note 135 fd_13 is listed on the night office key register
note 136 pl_0217 was photographed for the condition file
note 137 the lid gasket of pl_0203 is due for replacement next season
note 138 pl_0010 was photographed for the condition file
note 139 the lid gasket of pl_0105 is due for replacement next season
note 140 pl_0103 was photographed for the condition file
note 141 the lid gasket of pl_0122 is due for replacement next season
note 142 pl_0158 was photographed for the condition file
note 143 the lid gasket of pl_0121 is due for replacement next season
note 144 pl_0206 was photographed for the condition file
note 145 the lid gasket of pl_0045 is due for replacement next season
note 146 pl_0203 was photographed for the condition file
note 147 the lid gasket of pl_0207 is due for replacement next season
note 148 pl_0054 was photographed for the condition file
note 149 the lid gasket of pl_0079 is due for replacement next season
note 150 pl_0190 was photographed for the condition file
note 151 the lid gasket of pl_0028 is due for replacement next season
note 152 pl_0089 was photographed for the condition file
note 153 the lid gasket of pl_0202 is due for replacement next season
note 154 pl_0079 was photographed for the condition file
note 155 the lid gasket of pl_0134 is due for replacement next season
note 156 pl_0083 was photographed for the condition file
note 157 the lid gasket of pl_0201 is due for replacement next season
note 158 pl_0222 was photographed for the condition file
note 159 the lid gasket of pl_0001 is due for replacement next season
note 160 pl_0098 was photographed for the condition file
note 161 the lid gasket of pl_0133 is due for replacement next season
note 162 pl_0056 was photographed for the condition file
note 163 the lid gasket of pl_0083 is due for replacement next season
note 164 pl_0112 was photographed for the condition file