

INDEPENDENT CARGO INSPECTION REPORT

Report: IR-260518-44 Claim: FCL-2026-0147

Inspection date: 2026-05-18 Location: MetroMart DC18, Dallas, TX

PRO: BLF-77209115 BOL: BOL-884219

Inspector: Southwest Cargo Survey LLC / L. Greene

Observed shipment condition

- Consignee records 58 of 60 cartons received; 2 cartons not present at inspection.
- Five cartons showed crush, puncture and/or moisture damage: C-017, C-018, C-021, C-022, C-023.
- Internal molded foam inserts were present in all five opened cartons.
- No evidence of product damage was observed in the 6 units classified as repackable.

Unit disposition

Carton	Units	Unsellable	Repackable	Primary observation
C-017	4	3	1	Corner crush / shell deformation
C-018	4	2	2	Moisture + retail box damage
C-021	4	4	0	Puncture / cracked housings
C-022	4	2	2	Compression / retail box damage
C-023	4	3	1	Side crush / screen damage

TOTAL: 20 units examined; 14 unsellable; 6 functional but require repacking.

Cost documentation supplied by Northstar

Inspection fee: \$420.00 Repack labor: \$300.00

Inspector conclusion

The observed physical damage is consistent with compression/puncture during handling or transit.
The presence of molded foam provides some internal protection; however, no vendor packaging specification or laboratory packaging test was provided to the inspector.

Photos supplied to surveyor: only C-021 and C-023.

Signed: L. Greene 05/18/2026