1

GATE NM-54 2022

EE23BTECH11011- Batchu Ishitha*

Q: A system with two degrees of freedom, as shown in the figure, has masses $m_1 = 200kg$ and $m_2 = 100kg$ and stiffness coefficients $k_1 = k_2 = 200N/m$. Then the lowest natural frequency of the system is _____ rad/s (rounded off to one decimal place).




Fig. 0.

GATE NM 2022

Solution:




Fig. 0.

METHOD-1:

Variable	Description	Value
m_1	Mass of block 1	200kg
m_2	Mass of block 2	100kg
k_1	Stiffness coefficient of spring1	200N/m
k_2	Stiffness coefficient of spring2	200N/m

TABLE 0 Input Parameters

$$m_1 \ddot{x}_1(t) - k_2 (x_2(t) - x_1(t)) + k_1 x_1(t) = 0$$
 (1)
$$m_2 \ddot{x}_2(t) + k_2 (x_2(t) - x_1(t)) = 0$$
 (2)

Writing (1) and (2) in matrix form:

$$\begin{pmatrix} m_1 & 0 \\ 0 & m_2 \end{pmatrix} \begin{pmatrix} \ddot{x}_1(t) \\ \ddot{x}_2(t) \end{pmatrix} + \begin{pmatrix} k_1 + k_2 & -k_2 \\ -k_2 & k_2 \end{pmatrix} \begin{pmatrix} x_1(t) \\ x_2(t) \end{pmatrix} = \begin{pmatrix} 0 \\ 0 \end{pmatrix}$$
 (3)

$$x(t) \stackrel{\mathcal{L}}{\longleftrightarrow} X(s)$$
 (4)

$$x''(t) \stackrel{\mathcal{L}}{\longleftrightarrow} s^2 X(s) - sx(0) - x'(0)$$
 (5)

Applying Laplace transform for (1) and (2) assuming they are at their repective maximum displacement at t=0

$$m_1 \left(s^2 X_1(s) - s x_1(0) - 0 \right) - k_2 \left(X_2(s) - X_1(s) \right) + k_1 X_1(s) = 0$$

$$(6)$$

$$m_2 \left(s^2 X_2(s) - s x_2(0) - 0 \right) + k_2 \left(X_2(s) - X_1(s) \right) = 0$$

$$(7)$$

Writing (6) and (7) in matrix form:

$$\begin{pmatrix} m_1 s^2 + (k_1 + k_2) & -k_2 \\ -k_2 & m_2 s^2 + k_2 \end{pmatrix} \begin{pmatrix} X_1(s) \\ X_2(s) \end{pmatrix} = \begin{pmatrix} m_1 s x_1(0) \\ m_2 s x_2(0) \end{pmatrix}$$
(8)

$$\begin{pmatrix} X_1(s) \\ X_2(s) \end{pmatrix} = \frac{1}{m_1 m_2 s^4 + (k_1 + k_2) m_2 s^2 + k_2 m_1 s^2 + k_1 k_2}
\begin{pmatrix} m_2 s^2 + k_2 & k_2 \\ k_2 & m_1 s^2 + (k_1 + k_2) \end{pmatrix} \begin{pmatrix} m_1 s x_1(0) \\ m_2 s x_2(0) \end{pmatrix}$$
(9)

$$\implies X_1(s) = \frac{m_1 m_2 s^3 x_1(0) + k_2 m_1 s x_1(0) + m_2 k_2 s x_2(0)}{m_1 m_2 s^4 + (k_1 + k_2) m_2 s^2 + k_2 m_1 s^2 + k_1 k_2}$$

$$(10)$$

$$m_1 k_2 s x_1(0) + m_1 m_2 s^3 x_2(0) + (k_1 + k_2) m_2$$

(1)
$$\implies X_2(s) = \frac{m_1 k_2 s x_1(0) + m_1 m_2 s^3 x_2(0) + (k_1 + k_2) m_2 s x_2(0)}{m_1 m_2 s^4 + (k_1 + k_2) m_2 s^2 + k_2 m_1 s^2 + k_1 k_2}$$
(2) (11)

Considering denominator of $X_i(s)$ for i = 1, 2(ie: characteristic equation of the system):

$$m_1 m_2 s^4 + (k_1 + k_2) m_2 s^2 + k_2 m_1 s^2 + k_1 k_2 = 0$$
 (12)

$$s^4 + 4s^2 + 2 = 0 \tag{13}$$

but we know, $i = \frac{dq}{dt}$

$$\implies L_1\ddot{q}_1 - k_2(q_2 - q_1) + k_1q_1 = 0$$
 (20)

$$\implies L_2 \ddot{q}_2 + k_2 (q_2 - q_1) \ dt = 0 \tag{21}$$

Writing (20) and (21) in matrix form:

$$\implies s^{2} = \frac{-4 \pm \sqrt{16 - 8}}{2} \begin{pmatrix} L_{1} & 0 \\ 0 & L_{2} \end{pmatrix} \begin{pmatrix} \dot{q}_{1}(t) \\ \dot{q}_{2}(t) \end{pmatrix} + \begin{pmatrix} k_{1} + k_{2} & -k_{2} \\ -k_{2} & k_{2} \end{pmatrix} \begin{pmatrix} q_{1}(t) \\ q_{2}(t) \end{pmatrix} = \begin{pmatrix} 0 \\ 0 \\ (22) \end{pmatrix}$$

$$= -2 \pm \sqrt{2}$$
(15)
$$q(t) \stackrel{\mathcal{L}}{\longleftrightarrow} Q(s) \tag{23}$$

The roots of s are imaginary so it's Sinusoid.

$$\omega = \pm \sqrt{2 \mp \sqrt{2}} \tag{16}$$

$$\implies \omega_{least} = 0.765 rad/s$$
 (17)

METHOD-2:CONVERTING MECHANICAL SYSTEM INTO ITS ANALOGOUS ELECTRICAL CIRCUIT BY FORCE VOLTAGE METHOD

Mechanical Quantity	Electrical Quantity	
Force	Voltage	
Velocity	Current	
Mass	Inductance	
Stiffness coefficient of spring	Reciprocal of Capacitance	

TABLE 0 Input Parameters




Fig. 0.

$$k_1 \int i_1 dt + L_1 \frac{di_1}{dt} + k_2 \int (i_1 - i_2) dt = 0$$
 (18)
$$L_2 \frac{di_2}{dt} - k_2 \int (i_1 - i_2) dt = 0$$
 (19)

$$q^{''}(t) \stackrel{\mathcal{L}}{\longleftrightarrow} s^{2}Q(s) - sq(0) - q^{'}(0)$$
 (24)

Assuming charge to be maximum at t=0;

$$L_1(s^2Q_1(s) - sq_1(0)) - k_2(Q_2(s) - Q_1(s)) + k_1Q_1(s) = 0$$
(25)

$$L_2(s^2Q_2(s) - sq_2(0)) + k_2(Q_2(s) - Q_1(s))$$
= 0
(26)

Writing (25) and (26) in matrix form:

$$\begin{pmatrix} L_1 s^2 + (k_1 + k_2) & -k_2 \\ -k_2 & L_2 s^2 + k_2 \end{pmatrix} \begin{pmatrix} Q_1(s) \\ Q_2(s) \end{pmatrix} = \begin{pmatrix} L_1 s q_1(0) \\ L_2 s q_2(0) \end{pmatrix}$$
(27)

$$\begin{pmatrix} Q_{1}(s) \\ Q_{2}(s) \end{pmatrix} = \frac{1}{L_{1}L_{2}s^{4} + (k_{1} + k_{2})L_{2}s^{2} + k_{2}L_{1}s^{2} + k_{1}k_{2}}$$

$$\begin{pmatrix} L_{2}s^{2} + k_{2} & k_{2} \\ k_{2} & L_{1}s^{2} + (k_{1} + k_{2}) \end{pmatrix} \begin{pmatrix} L_{1}sq_{1}(0) \\ L_{2}sq_{2}(0) \end{pmatrix}$$
(28)

$$\Rightarrow Q_{1}(s) = \frac{L_{1}L_{2}s^{3}q_{1}(0) + k_{2}L_{1}sq_{1}(0) + k_{2}L_{2}sq_{2}(0)}{L_{1}L_{2}s^{4} + (k_{1} + k_{2})L_{2}s^{2} + k_{2}L_{1}s^{2} + k_{1}k_{2}}$$

$$(29)$$

$$\Rightarrow Q_{2}(s) = \frac{k_{2}L_{1}sq_{1}(0) + L_{1}L_{2}s^{3}q_{2}(0) + (k_{1} + k_{2})L_{2}sq_{2}(0)}{L_{1}L_{2}s^{4} + (k_{1} + k_{2})L_{2}s^{2} + k_{2}L_{1}s^{2} + k_{1}k_{2}}$$

Considering denominator of $Q_i(s)$ for i = 1, 2(ie: characteristic equation of the system):

$$L_1 L_2 s^4 + (k_1 + k_2) L_2 s^2 + k_2 L_1 s^2 + k_1 k_2 = 0$$
 (31)

$$s^4 + 4s^2 + 2 = 0 ag{32}$$

$$\implies s^2 = \frac{-4 \pm \sqrt{16 - 8}}{2 (33)}$$
$$= -2 \pm \sqrt{2} (34)$$

The roots of s are imaginary so it's Sinusoid.

$$\omega = \pm \sqrt{2 \mp \sqrt{2}} \tag{35}$$

$$\implies \omega_{least} = 0.765 rad/s$$
 (36)

DOUBT:

$$\begin{pmatrix} m_1 & 0 \\ 0 & m_2 \end{pmatrix} \begin{pmatrix} \ddot{x_1}(t) \\ \ddot{x_2}(t) \end{pmatrix} + \begin{pmatrix} k_1 + k_2 & -k_2 \\ -k_2 & k_2 \end{pmatrix} \begin{pmatrix} x_1(t) \\ x_2(t) \end{pmatrix} = \begin{pmatrix} 0 \\ 0 \end{pmatrix}$$
(37)

Directly substituting $x'' = -\omega^2 x$

$$\begin{pmatrix} -m_1\omega^2 + k_1 + k_2 & -k_2 \\ -k_2 & -m_2\omega^2 + k_2 \end{pmatrix} \begin{pmatrix} x_1(t) \\ x_2(t) \end{pmatrix} = \begin{pmatrix} 0 \\ 0 \end{pmatrix} (38)$$

And then substituting $s = j\omega$;

$$\begin{pmatrix} m_1 s^2 + k_1 + k_2 & -k_2 \\ -k_2 & m_2 s^2 + k_2 \end{pmatrix} \begin{pmatrix} x_1(t) \\ x_2(t) \end{pmatrix} = \begin{pmatrix} 0 \\ 0 \end{pmatrix}$$
 (39)

But when i apply laplace transform and then write in a matrix with our assumption ie:

$$\begin{pmatrix} X_1(s) \\ X_2(s) \end{pmatrix} = \frac{1}{m_1 m_2 s^4 + (k_1 + k_2) m_2 s^2 + k_2 m_1 s^2 + k_1 k_2}
\begin{pmatrix} m_2 s^2 + k_2 & k_2 \\ k_2 & m_1 s^2 + (k_1 + k_2) \end{pmatrix} \begin{pmatrix} m_1 s x_1(0) \\ m_2 s x_2(0) \end{pmatrix}
(40)$$

These both are also not matching... Is there any error in this..