

DEFECTRA VEHICLE INSPECTION REPORT

Vehicle Information

Brand	4r3
Model	r34r43
Plate	434r
Year	None
Inspection Date	2026-08-22

Detected Defects

Defect	Confidence	Severity
Crack	96.69 %	HIGH

Inspection Summary

****Vehicle Inspection Report****
****Inspection Date:**** 22 August 2026
****Vehicle Identification:****
- ****Brand:**** 4r3
- ****Model:**** r34r43
- ****Plate:**** 434r
- ****Year:**** Not specified

1. Inspection Summary

During the automated inspection conducted on 22 August 2026, a single defect was identified:

Defect	Confidence	Severity	Location	Description (translated)
Crack	96.69 %	HIGH	Central body panel	A fissure detected at the centre of the bodywork, indicating a potential structural failure. The central position suggests that the crack could compromise the overall rigidity of the vehicle and occupant safety.

The detection confidence is well above the 90 % threshold typically used to flag high severity issues, confirming the reliability of the finding. The automated system's performance aligns with the documented trend that higher confidence levels correlate with increased accuracy, even though coverage for minor damage classes is lower. In this case, the defect is clearly classified as high severity, mitigating concerns about low coverage classes.

2. Overall Vehicle Condition

- **Structural Integrity:** The presence of a high-severity crack in the central body panel raises immediate concerns about the vehicle's structural integrity.
- **Safety Impact:** A crack in this location can affect the vehicle's crash-worthiness, potentially endangering occupants.
- **Remaining Components:** No other defects were detected during this inspection cycle. However, the absence of additional findings does not preclude the existence of unseen damage; periodic reinspection is advised.

Conclusion: The vehicle exhibits a critical structural defect that requires prompt professional evaluation and remediation.

3. Maintenance Recommendations

1. Immediate Professional Inspection

- **Scope:** Measure crack length, depth, and extent; assess surrounding material integrity.
- **Tools:** High-resolution imaging (e.g., CT or ultrasonic), mechanical testing rigs.

2. Repair Options

- **Welding:** If the crack is confined to a single panel and the material is suitable for fusion, spot or seam welding may restore structural continuity.
- **Panel Bonding:** For cracks that are too deep for welding or where welding would compromise aesthetics, high-strength adhesive bonding can be employed.
- **Panel Replacement:** If the crack is extensive or the panel's structural role is compromised, replace the entire panel.

3. Post-Repair Verification

- **Mechanical Strength Test:** Conduct a load-bearing test (e.g., bending or torsion) to confirm that the repaired area meets original specifications.
- **Visual & Non-Destructive Inspection:** Verify that the repair does not introduce new defects.

4. Follow-Up Schedule

- **Short-Term:** Reinspect the repaired area after 30 days to ensure no early failure.
- **Long-Term:** Include the vehicle in the next scheduled automated inspection cycle (typically every 6–12 months) to monitor for recurrence or new damage.

5. Documentation & Record-Keeping

- Maintain detailed records of measurements, repair procedures, and test results for future reference and potential resale or insurance purposes.

Prepared by:

[Your Name] – Automotive Inspection Specialist

[Company/Organization]

[Contact Information]

This report is based on the automated detection system's findings and the accompanying expert recommendations. For definitive safety assurance, a qualified automotive repair professional should perform the outlined inspections and repairs.

Overall Condition

Fair

Maintenance Recommendation

- Crack: Il est recommandé de procéder à une inspection détaillée par un professionnel pour mesurer la longueur, la profondeur et l'étendue de la fissure. Selon l'évaluation, la réparation peut consister en un soudage de la zone endommagée, un collage de panneaux ou, si la fissure est trop importante, le remplacement complet du panneau concerné. Une fois réparé, un contrôle de la résistance mécanique doit être effectué.

*Generated automatically by DEFECTRA AI
22/08/2026 15:20*