

DEFECTRA VEHICLE INSPECTION REPORT

Vehicle Information

Brand	rtvyu
Model	tfgh
Plate	3456
Year	None
Inspection Date	2026-08-22

Detected Defects

Defect	Confidence	Severity
Crack	96.69 %	HIGH

Inspection Summary

Vehicle Inspection Report
Vehicle: rtvyu tfgh – Plate 3456
Inspection Date: 2026-08-22

1. Inspection Summary

During the automated inspection, the system identified a **high severity crack** located at the center-middle of the vehicle's body panel.

- **Confidence:** 96.69 %
- **Severity:** HIGH
- **Detected area:** Extended, suggesting a substantial structural compromise.

The detection algorithm flagged the crack with a very high confidence level, indicating that the defect is unlikely to be a false positive. The bounding box covers a sizeable portion of the panel, reinforcing the assessment that the crack is significant.

2. Overall Vehicle Condition

Item	Status	Notes
Body Integrity	Compromised	The crack is located in a critical structural area.
Structural Safety	At Risk	If the crack propagates, it could affect load-bearing capacity.
Vehicle Age	Unknown	Year not provided; however, the presence of a high severity crack warrants immediate attention regardless of age.
Other Defects	None Detected	No additional defects were reported by the inspection

system. |

****Conclusion:**** The vehicle exhibits a critical structural defect that poses a safety risk. Immediate professional evaluation and repair are required.

3. Maintenance Recommendations

1. ****Immediate Visual Inspection****

- A qualified body shop technician should perform a detailed visual and tactile inspection of the cracked area to assess depth, extent, and whether the crack penetrates structural members.

2. ****Repair Method****

- ****Welding****: If the crack is confined to the panel and does not compromise underlying structural members, spot or seam welding can restore integrity.

- ****Panel Replacement****: If the crack is deep, extends through the panel thickness, or involves structural components, replace the entire panel.

- ****Hybrid Approach****: In some cases, a combination of welding and panel reinforcement (e.g., adding a backing plate) may be optimal.

3. ****Post-Repair Verification****

- ****Strength Test****: Conduct a non-destructive test (e.g., ultrasonic or magnetic particle inspection) to confirm weld integrity or panel replacement quality.

- ****Alignment Check****: Verify that the repaired panel aligns with adjacent panels and that the vehicle's body geometry remains within manufacturer tolerances.

4. ****Documentation****

- Record all repair steps, materials used, and test results. This documentation is essential for future inspections and potential resale value.

5. ****Follow-Up Inspection****

- Schedule a follow-up inspection 30–60 days after repair to ensure no secondary damage has developed.

Final Note

Given the high confidence and severity rating, delaying repair could lead to further structural failure and compromise occupant safety. Prompt action is strongly advised.

Overall Condition

Fair

Maintenance Recommendation

• **Crack**: Il est recommandé de procéder à une inspection visuelle détaillée par un professionnel, puis de réparer la fissure par soudage ou par remplacement de la partie endommagée. Si la fissure est profonde ou traverse des éléments structuraux, un remplacement complet du panneau concerné est conseillé. Après réparation, un contrôle de la résistance et une vérification de l'alignement doivent être effectués.

Generated automatically by DEFECTRA AI
22/08/2026 16:07