Because the ends of a meterstick can be easily damaged or worn, it is best to minimize instrument error by making measurements with a portion of the scale that is in the middle of the meterstick. Instead of measuring from the end (0 cm), try measuring from the 10 cm line.

Precision describes the limitations of the measuring instrument

Poor accuracy involves errors that can often be corrected. On the other hand, precision describes how exact a measurement can possibly be. For example, a measurement of 1.325 m is more precise than a measurement of 1.3 m. A lack of precision is typically due to limitations of the measuring instrument and is not the result of human error or lack of calibration. For example, if a meterstick is divided only into centimeters, it will be difficult to measure something only a few millimeters thick with it.

In many situations, you can improve the precision of a measurement. This can be done by making a reasonable estimation of where the mark on the instrument would have been. Suppose that in a laboratory experiment you are asked to measure the length of a pencil with a meterstick marked in centimeters, as shown in **Figure 11.** The end of the pencil lies somewhere between 18 cm and 18.5 cm. The length you have actually measured is slightly more than 18 cm. You can make a reasonable estimation of how far between the two marks the end of the pencil is and add a digit to the end of the actual measurement. In this case, the end of the pencil seems to be less than halfway between the two marks, so you would report the measurement as 18.2 cm.

Significant figures help keep track of imprecision

It is important to record the precision of your measurements so that other people can understand and interpret your results. A common convention used in science to indicate precision is known as **significant figures.**

In the case of the measurement of the pencil as about 18.2 cm, the measurement has three significant figures. The significant figures of a measurement include all the digits that are actually measured (18 cm), plus one *estimated* digit. Note that the number of significant figures is determined by the precision of the markings on the measuring scale.

The last digit is reported as a 0.2 (for the estimated 0.2 cm past the 18 cm mark). Because this digit is an estimate, the true value for the measurement is actually somewhere between 18.15 cm and 18.25 cm.

When the last digit in a recorded measurement is a zero, it is difficult to tell whether the zero is there as a place holder or as a significant digit. For example, if a length is recorded as 230 mm, it is impossible to tell whether this number has two or three significant digits. In other words, it can be difficult to know whether the measurement of 230 mm means the measurement is known to be between 225 mm and 235 mm or is known more precisely to be between 229.5 mm and 230.5 mm.




Figure 11
Even though this ruler is marked in only centimeters and half-centimeters, if you estimate, you can use it to report measurements to a precision of a millimeter.

significant figures

those digits in a measurement that are known with certainty plus the first digit that is uncertain