SVG Prep Checklist for Laser Cutting with xTool Creative Space

This checklist helps ensure smooth importing and correct operation setup in XCS.

Basic Cleanup

- [] Convert all text to paths/outlines
 - Prevents font substitution or missing text on other computers.
- [] Ungroup and flatten
 - Eliminate groups, layers, masks, and compound paths if possible.
- [] Remove clipping masks and filters
 - These can confuse XCS or cause missing elements.
- [] Clean metadata and hidden layers
 - Use "Save As → Plain SVG" if exporting from Inkscape or Illustrator.

Color & Stroke Guidelines (for XCS)

- [] Use clear stroke/fill colors to represent different operations
 While XCS doesn't auto-map black = engrave, distinct colors help you separate layers
 manually.
- [] Optional: Use thin strokes (e.g., 0.1 mm) for cuts, filled shapes for engraves
 This improves visual clarity, though not required for XCS recognition.
- [] Avoid semi-transparent fills

 XCS does not interpret opacity the way design tools do.



• [] Set artboard/document size to match project (mm or inches)

Avoid unexpected scaling — match XCS workspace units.

Test Before Running

Always test one of your SVGs in XCS after export to verify:

- Visibility of all parts
- No missing paths
- Correct alignment and sizing