

CRITICAL INCIDENT: EMERGENCY TRIP REPORT

Timestamp: 2026-09-30 06:27:24 UTC

Injected Failure: Sudden Bearing Seizure

Automation Response: EMERGENCY SHUTDOWN TRIGGERED

Final Telemetry Snapshot Prior to Interlock:

- health_status: CRITICAL
- vibration_rms: 48.6
- bearing_temp: 142.0
- pressure_differential: 1.2
- flow_rate: 450.0
- emergency_shutdown_active: True
- last_fault: Sudden Bearing Seizure