# DESERT SUN DIESEL REPAIR

"We come to you" - Tucson AZ - 520-555-0175

| | | | |
|---|---|---|---|
| **INVOICE #** | DS-1189 | **DATE:** | 9-3-2026 |
| **CUSTOMER:** | Ryder - Tucson yard | | |
| **FLEET #:** | 6620 | **VIN:** | 1HTMMAAL5KH660112 |

| Description of Work | Charge |
|---|---|
| Weld cracked driver-side step bracket - 1.5 hrs @ $95 | $142.50 |
| Steel plate & mounting hardware | $38.00 |
| Replace both headlight assemblies - 0.7 hr @ $95 | $66.50 |
| Headlamp assy LH  pn HL-4410L  1 @ $189.00 | $189.00 |
| Headlamp assy RH  pn HL-4410R  1 @ $189.00 | $189.00 |
| Mobile service charge | $65.00 |

| | |
|---|---|
| SUBTOTAL | $690.00 |
| TAX 8.6% (parts only) | $35.78 |
| INVOICE TOTAL | $725.78 |
| LESS DEPOSIT RECEIVED 8/28 | -$300.00 |
| **BALANCE DUE** | **$425.78** |

Note: passenger mirror arm loose - can tighten next visit, no charge quoted.
Thank you! Pay by check or card. Ask for Ray.