









INT	SO/
RST	MOSI
ОХЯ	MISO
RX1	SCK
-BF GND	GND
3.30	3.3V
гртя	
охт	MODE O
TX1	MODE 1
TX2	
SOF	OSC_IN
GND	GND
3.30	3.3V