

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: Jean Polini

Responsável/cliente: Marcos Roberto Goncalvez Vieira GRE/Prodemge: João Antinossi

> Plataforma Consórcio **VSAT-ID** Porta kbps EMC/Vodanet **VSAT** SEE-URIA-22289 2Mbps





PRTG Traffic Grapher V6.2.0.907 - 11/2/2017 1:49:44 PM

Satellite (DVB) RX Configuration ______

Auto start . Enable:
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

: On Rx State

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

: 12.176518 GHz

Symbol Rate : 4 882114

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 16.7 dB SNR : -34 dBm Input Power

dvb tx show

```
Satellite (DVB) TX Configuration
-----
                    : Enabled
Auto start
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm EIRP : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -15.4 dBm
ODU Output Power : 33.2 dBm
EIRP
                     : 46.5 dBW
Es/No
                     : 13.5 dB
\hbox{\tt Header Compression} \quad \hbox{\tt : Disabled} \quad \hbox{\tt - HC for RCS2 not supported by HUB}
Timing correction : -463 us (282035 us)
Frequency correction: 120 Hz
# device show
System Information:
                        : SEE-URIA-22289
    Name
    Location
                         : URUCUIA
    Contact
    System Up time : 0 days, 00:15:15 CPU Load : 6%
    System time(UTC) : 02 November 2017 13:39:14 Broadcast Message : not set
HW:
   Model
                        : SatLink 2000
                        : 120033
    HW ID
    Main board ID
                        : 120026 R6.1
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:49:e6
Satellite (DVB) : 00:20:0e:10:49:e6
   Ethernet (LAN)
Transec not Supported by this device !
# arp show
   NetAddr
                State MacAddr
   10.213.88.2 Dynamic 64:1c:67:62:2e:12 1
#
Pinging 10.213.88.1 with 32 bytes of data:
Reply from 10.213.88.1: bytes=32 time=598ms TTL=56
Reply from 10.213.88.1: bytes=32 time=563ms TTL=56
Reply from 10.213.88.1: bytes=32 time=592ms TTL=56
Reply from 10.213.88.1: bytes=32 time=595ms TTL=56
Reply from 10.213.88.1: bytes=32 time=603ms TTL=56
Reply from 10.213.88.1: bytes=32 time=575ms TTL=56
Reply from 10.213.88.1: bytes=32 time=576ms TTL=56
Reply from 10.213.88.1: bytes=32 time=584ms TTL=56
Reply from 10.213.88.1: bytes=32 time=600ms TTL=56
Reply from 10.213.88.1: bytes=32 time=584ms TTL=56
Reply from 10.213.88.1: bytes=32 time=607ms TTL=56
```

```
Ping statistics for 10.213.88.1:

Packets: Sent = 11, Received = 11, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 563ms, Maximum = 607ms, Average = 588ms
```

Lista de sites acessados:

www.globo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.mg.gov.br - ok

Responsável pelo teste de navegação: Nome: MARCOS ROBERTO GONCALVEZ VIEIRA

Função: VICE DIRETOR Masp: 1127229-1

Funcionamento: 08:00 às 12:30h