


TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Jean Polini

Responsável/cliente: Victor Vieira Ribeiro GRE/Prodemge: João Antinossi

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet **VSAT** SEE-CAAI-22921 2Mbps





Satellite (DVB) RX Configuration _____ Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

: On
: On
: Forward link up
Network : 65281, Prodemge@Vodanet
Frequency : 12.176439 GHz
Symbol Rate : 4.883006 Mcc.

- receiving : 20 16APSK-4/5 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 15.9 dB SNR : -42 dBm Input Power

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-RCS2)
IDU Output Power : -20.1 dBm
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -226 us (280568 us)
Frequency correction: 240 Hz
System Information:
   Name
                        : SEE-CAAI-22921
    Location
                         : Carai - MG
    Contact
   System Up time : 0 days, 00:08:31
CPU Load : 15%
System time(UTC) : 24 November 2017 18:03:11
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
                        : 120026 R6.2
    Main board ID
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:59:21
Satellite (DVB) : 00:20:0e:10:59:21
NetAddr
          State MacAddr
   10.215.101.2 Dynamic 64:1c:67:62:2e:12 1
Pinging 10.215.101.1 with 32 bytes of data:
Reply from 10.215.101.1: bytes=32 time=521ms TTL=56
Reply from 10.215.101.1: bytes=32 time=646ms TTL=56
Reply from 10.215.101.1: bytes=32 time=558ms TTL=56
Reply from 10.215.101.1: bytes=32 time=626ms TTL=56
Reply from 10.215.101.1: bytes=32 time=534ms TTL=56
Reply from 10.215.101.1: bytes=32 time=532ms TTL=56
Reply from 10.215.101.1: bytes=32 time=548ms TTL=56
Reply from 10.215.101.1: bytes=32 time=546ms TTL=56
Reply from 10.215.101.1: bytes=32 time=560ms TTL=56
Reply from 10.215.101.1: bytes=32 time=570ms TTL=56
Ping statistics for 10.215.101.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 521ms, Maximum = 646ms, Average = 564ms
```

Lista de sites acessados:
<u>www.globo.com</u> – ok
<u>www.yahoo.com</u> – ok
<u>www.hotmail.com</u> – ok
<u>www.google.com</u> – ok
<u>www.educacao.mg.gov.br</u> – ok
<u>www.prodemge.gov.br</u> – ok
Responsável pelo teste de navegação:
Nome: Victor Vieira Ribeiro
Função: Diretor
MASP: 11389939
Telefone: 33-99908781
Funcionamento: 07:00h às 18:30h